

Module Description:

In this module a simple milling machine with the axes X1, Y1 and Z1, the rotary axes A1, C1 and the main spindle SP1 is to be setup for milling. The individual commissioning steps are to be checked from time to time to show the result of the parameterization.

The preparation of the tool list, the cycle selections, the block search and various basic settings are also part of the training scope. There will be a detailed description of the selections to be made for JOG-TSM.

Module Objective:

By means of this module you will learn and get to know the meaning of the Machine and Setting data to be used as well as the various means available in order to configure the machine to suit the particular requirements.

The functions will be parameterized in several blocks and subsequently tested to check correct working.

Content:

Menu and Technology settings

Manufacturer Cycles

Setup for Milling

Cycle settings


Tool List Setup


Basic Settings

JOG-TSM

Block Search

Simulation





Notes

[Overview Machine data and setting data](#)

Basic settings Machine data/setting data

| MD | Identifier | Default | Settings Milling | Description |
|-------|---------------------------------|--|--|--|
| 10260 | \$MN_CONVERT_SCALING_SYSTEM | 0 | 1 | Enable basic system conversion |
| 10602 | \$MN_FRAME_GEOAX_CHANGE_MODE | 0 | 1 | Frames when changing geometry axes |
| 10714 | \$MN_M_NO_FCT_EOP | -1 | 32 | M function for spindle active after reset |
| 10715 | \$MN_M_NO_FCT_CYCLE[0] | -1 | 6 | M function to be replaced by a subroutine |
| 10716 | \$MN_M_NO_FCT_CYCLE_NAME[0] | “ “ | L6 | Subroutine name for M function replacement |
| 10722 | \$MN_AXCHANGE_MASK | 0H | 4H | Bit 2 = 1: Parameters for axis replacement behavior |
| 11410 | \$MN_SUPPRESS_ALARM_MASK | 108000H | 108003H | Bit 0: 15110: REORG not possible Bit 1: 10763 The path component of the block in the contour plane is zero Bit 15: 5000 Communication order cannot be executed Bit 20: 2900 Reboot is delayed |
| 11450 | \$MN_SEARCH_RUN_MODE | 0H | 7H | Bit 0 = 1: Machining is stopped with the loading of the last action block after search run Bit 1 = 1: Automatic ASUP start after output of the action blocks Bit 2 = 1: The output of the auxiliary functions in the action blocks is suppressed |
| 17530 | \$MN_TOOL_DATA_CHANGE_COUNTER | 1FH | 1FH | Mark tool data change for HMI |
| 18080 | \$MN_MM_TOOL_MANAGEMENT_MASK | 0H | BH | Bit 0 = 1: Memory for TM-specific data is provided Bit 1 = 1: Memory for monitoring data (WZMO) is provided Bit 3 = 1: Memory to consider adjacent location is provided |
| 19320 | \$ON_TECHNO_FUNCTION_MASK | 0H | Bit 4 = 1 | Bit 4 = 1: Tool management with magazine data enabled |
| 20110 | \$MC_RESET_MODE_MASK | 1H | 4041H | Bit 0 = 1: G codes acc. to \$MC_GCODE_RESET_VALUE Bit 6 = 1: Current setting for active tool length offset is retained after reset/end-of-part-program Bit 14 = 1: The current setting of the basic frame is retained |
| 20128 | \$MC_COLLECT_TOOL_CHANGE | 1 | 0 | No tool change commands after search run |
| 20130 | \$MC_CUTTING_EDGE_RESET_VALUE | 0 | 1 | Tool and cutting edge remain activated |
| 20150 | \$MC_G_CODE_RESET_VALUE | [15] = 1 [21] = 1 [41] = 1 [51] = 1 [52] = 1 | [15] = 3 [21] = 2 [41] = 1 [51] = 1 [52] = 1 | Group 16: Feedrate override 3 = CFIN Group 22: Tool offset type 2 = CUT2DF Group 42 Toolholder 1 = TCOABS (for swivel) Group 52: Frame rotation in relation to workpiece 1 = PAROTOF (2 = PAROT, for swivel) Group 53: Frame rotation in relation to tool 1 = TOROTOF (for swivel) |
| 20152 | \$MC_G_CODE_RESET_MODE | [5] = 0 [7] = 0 [12] = 0 [21] = 0 | [5] = 1 [7] = 1 [12] = 0 [21] = 0 | Group 6: Plane selection remains active after Reset Group 8: Zero point offset remains active after Reset Group 13: Work piece dimensioning inch/metric default after reset Group 22: Tool correction type default after reset |
| 20202 | \$MC_WAB_MAXNUM_DUMMY_BLOCKS | 5 | 10 | maximum number of blocks w/o traversing movement with SAR |
| 20240 | \$MC_CUTCOM_MAXNUM_CHECK_BLOCKS | 4 | 4 | Blocks for look-ahead contour calculation with TRC |
| 20250 | \$MC_CUTCOM_MAXNUM_DUMMY_BLOCKS | 3 | 5 | maximum number of blocks without traversing motion in TRC |

Notes

Basic settings Machine data/setting data

| MD | Identifier | Default | Settings Milling | Description |
|-------|-----------------------------------|---------|------------------------|---|
| 20310 | \$MC_TOOL_MANAGEMENT_MASK | 0H | 80400BH | Bit 0 = 1: Tool management active Bit 1 = 1: Tool monitoring function active Bit 3 = 1: Consider adjacent location active Bit 14 = 1: automatic tool change during RESET and Start Bit 23 = 1: On offset selection no synchronization with HL |
| 20320 | \$MC_TOOL_TIME_MONITOR_MASK | 0H | 1H | Bit 0 = 1: Time monitoring for tool in tool holder 1 |
| 20734 | \$MC_EXTERN_FUNCTION_MASK | 0H | 8H | Function mask for external language Bit 3 = 1: Errors in ISO scanner are not output, the block is transferred to the Siemens translator. |
| 22550 | \$MC_TOOL_CHANGE_MODE | 0 | 1 | Tool change with M function |
| 22560 | \$MC_TOOL_CHANGE_M_CODE | 6 | 206 | M function for tool change |
| 24006 | \$MC_CHSFRAME_RESET_MASK | 1H | Bit 0 = 1 Bit 5 = 0 | Bit 0 = 1: System frame for actual value setting and scratching is active after reset. Bit 5 = 0: System frame for cycles is deleted on reset |
| 24007 | \$MC_CHSFRAME_RESET_CLEAR_MASK | 0H | Bit 0 = 0 Bit 5 = 1 | Bit 0 = 0: System frame for actual value setting and scratching is active after reset. Bit 5 = 1: System frame for cycles is deleted on reset |
| 24008 | \$MC_CHSFRAME_POWERON_MASK | 0H | 0H | Reset channel system frames after power on |
| 24030 | \$MC_FRAME_ACS_SET | 0 | 1 | Adjustment of SZS coordinate system - without cycle frames - with progr. offset |
| 27860 | \$MC_PROCESSTIMER_MODE | 0H | 73H | Bit 0 = 1: Measurement of total operating time is active for all part programs Bit 1 = 1: Measurement of current program runtime is active Bit 4 = 1: Measurement also with active dry run feed Bit 5 = 1: Measurement also with program test Bit 6 = 1: \$AC_CYCLE_TIME is not deleted on start by ASUP and PROG_EVENT |
| 27880 | \$MC_PART_COUNTER | 0H | 901H | Bit 0 = 1: Counter \$AC_REQUIRED_PARTS is activated Bit 8 = 1: Counter \$AC_ACTUAL_PARTS is active Bit 11 = 1: Increment \$AC_ACTUAL_PARTS with GOTOS |
| 28000 | \$MC_MM_REORG_LOG_FILE_MEM | 50 | 75 | Memory space for REORG (DRAM) |
| 28010 | \$MC_MM_NUM_REORG_MODULES | 8 | 20 | Number of blocks for local user variables in REORG (DRAM) |
| 28082 | \$MC_MM_SYSTEM_FRAME_MASK | 21H | 21H | Bit 0 = 1: System frame for setting actual value and scratching Bit 5 = 1: System frame for cycles |
| 28083 | \$MC_MM_SYSTEM_DATAFRAME_MASK | F9FH | F9FH | Bit mask for configuring channel-specific system frames in the data storage |
| 28450 | \$MC_MM_TOOL_DATA_CHG_BUFFER_SIZE | 400 | 400 | Buffer for tool data changes (DRAM) |
| 35040 | \$MA_SPIND_ACTIV_AFTER_RESET | 0 | 2 | Own spindle RESET |
| 42440 | \$SC_FRAME_OFFSET_INCR_PROG | 1 | 0 | Zero offsets in frames |
| 42442 | \$SC_TOOL_OFFSET_INCR_PROG | 1 | 0 | Tool length offsets |
| 42528 | \$SC_CUTCOM_DECEL_LIMIT | 0 | 1 | Feed lowering on circles with tool radius compensation |
| 42940 | \$SC_TOOL_LENGTH_CONST | 0 | 0 | Change of tool length components with change of active plane |
| 42950 | \$SC_TOOL_LENGTH_TYPE | 0 | 0 | Assignment of tool length compensation independent of tool type |



Notes

Basic settings Technology data

| MD | Identifier | Default | Settings Milling | Description |
|-------|---------------------------------|---------|------------------|---|
| 51024 | \$MNS_BLOCK_SEARCH_MODE_MASK_JS | 1H | | Bit mask for available search modes (ShopMill/ShopTurn) Bit 0: Block search with calculation without approach Bit 1: Block search with calculation with approach Bit 3: Skip EXTCALL programs Bit 5: Block search with test run |
| 51028 | \$MNS_BLOCK_SEARCH_MODE_MASK | 33H | | Bit mask for available block search modes Bit 0: Block search with calculation without approach Bit 1: Block search with calculation with approach Bit 3: Skip EXTCALL programs Bit 4: Block search without calculation Bit 5: Block search with test run |
| 51038 | \$MNS_SET_ACT_VALUE | 1 | | Set actual value selection 0 = Set actual value is not offered. 1 = If a user frame (settable work offset e.g. G54) is active, it will be used. In G500 Set actual values is not offered (system frame is no longer used). |
| 51039 | \$MNS_PROGRAM_CONTROL_MODE_MASK | 1H | | Options for machine - program influence: Bit 0: Program test function available |
| 51040 | \$MNS_SWITCH_TO_MACHINE_MASK | 0H | | Automatic operating area switchover to machine Bit 0: When selecting a program in the program manager, the operating area does not automatically switch over to Machine. Bit 1: When switching the type of operation via the MCP, the operating area is not automatically switched over to Machine. Bit 2: Do not switch automatically in Programs during program selection. Bit 3: No auto. Start of block search on selection / execution under Programs. |
| 51226 | \$MNS_FUNCTION_MASK_SIM | 0H | | Function mask Simulation Bit 0: No automatic start on simulation selection Bit 1: Deactivate simulation Bit 6: Enable handwheel as simulation override Bit 7: Interpretation of handwheel values as absolute values |
| 51228 | \$MNS_FUNCTION_MASK_TECH | 0H | | Function mask Cross-technology Bit 0: G code programming without multi-channel data Bit 1: Enable print function of editor |
| 52000 | \$MCS_DISP_COORDINATE_SYSTEM | 0 | 0 | 0: Vertical milling machine |
| 52005 | \$MCS_DISP_PLANE_MILL | 0 | 0 | 0: Plane selection on the operator panel 17: always G17 18: always G18 19: always G19 |
| 52200 | \$MCS_TECHNOLOGY | 0 | 2 | Technology 0: no specific configuration 1: turning 2: milling |
| 52201 | \$MCS_TECHNOLOGY_EXTENSION | 0 | 0 | Extended technology 0: no specific configuration 1: turning: extended technology Turning has not yet been implemented for Milling 2: milling |



Notes

Basic settings Technology data

| MD | Identifier | Default | Settings Milling | Description |
|-------|--------------------------|---------|--|--|
| 52206 | \$MCS_AXIS_USAGE | 0 | 0 | Meaning of the axes 0 = no special meaning; 1 = tool spindle (driven tool); 2 = C axis of the tool spindle (driven tool); 3 = main spindle (turning); 4 = C axis of the main spindle (turning); 5 = counterspindle (turning); 6 = C axis of the counterspindle (turning); 7 = linear axis of the counterspindle (turning); tailstock (turning); 9 = steady rest (turning); 10 = B axis (turning), 12 = B axis of the counter spindle (turning), 13 = Traverse travel X of the counter spindle (turning) |
| 52207 | \$MCS_AXIS_USAGE_ATTRIB | 0H | [0] = 0H -X [1] = 0H -Y [2] = 0H -Z [3] = 0H -SP1 [4] = 81H -A [5] = 44H -C | Axis attributes Bit 0: Rotates around the 1st geometry axis (applies to rotary axes) Bit 1: Rotates around the 2nd geometry axis (applies to rotary axes) Bit 2: Rotates around the 3rd geometry axis (applies to rotary axes) Bit 3: Positive direction of rotation is counterclockwise (applies to rotary axes) Bit 4: Displayed direction of rotation for M3 is counterclockwise (applies to spindles) Bit 5: Direction of rotation M3 corresponds to rotary axis minus (applies to spindles) This bit must be set analog to PLC bit DBnn.DBX17.6! (nn = 31 + machine data index) Bit 6: Show rotary axis as offset target for measruning Bit 7: Offer rotation axis in position pattern Bit 8: reserved Bit 9: Spindle is not SPOS-capable |
| 52210 | \$MCS_FUNCTION_MASK_DISP | 3H | 13H | Function mask Display Bit 0: Measuring system for programs always in the base system Bit 1: Face view when turning in the school coordinate system Bit 2: Hide "T,S,M" softkey in JOG area Bit 3: Generate automatic end-of-program in MDI Bit 4: Show follow-on tool in T,F,S window Bit 5: Hide softkey "Actual machine values" Bit 6: Hide tool radius/diameter in T,F,S window Bit 7: Hide tool length in T,F,S window Bit 8: Hide tool icon in T,F,S window |
| 52212 | \$MCS_FUNCTION_MASK_TECH | 0H | Bit 3 = 1 | Function mask Cross-technology Bit 0: Enable Swivel Bit 1: No optimized travel along software limit switches Bit 2: Approach logic for step drill (ShopTurn) Bit 3: Call block search cycle for ShopMill/ShopTurn Bit 4: Approach logic through cycle (ShopTurn) Bit 5: Call block search cycle for SERUPRO Bit 6: Work offset value ZV cannot be entered as an absolute value (ShopTurn) Bit 7: Detect the expiry of tool lives (ShopMill/ShopTurn) Bit 8: Manual machine (ShopMill/ShopTurn) Bit 9: Selection/deselection of work offset via softkey Bit 10: reserved Bit 11: Switch off layer check for drilling and milling tools (ShopTurn) |



Notes

Basic settings Technology data

| MD | Identifier | Default | Settings Milling | Description |
|-------|---------------------------------|---------|---------------------|--|
| 52214 | \$MCS_FUNCTION_MASK_MILL | 0H | | Function mask Milling Bit 0: Enable cylinder surface transformation (ShopMill) Bit 3: Enable inside/rear machining Bit 4: Enable spindle clamping (C axis) Bit 5: Enable spindle control of tool spindle via surface Bit 6: Enable spindle control of turning spindle via surface |
| 52216 | \$MCS_FUNCTION_MASK_DRILL | 0H | | Function mask Drilling Bit 0: CYCLE84 Unhide input fields Technology Bit 1: CYCLE840 Unhide input fields Technology |
| 52229 | \$MCS_ENABLE_QUICK_M_CODES | 0H | | Enable fast M functions Bit 0: Coolant OFF Bit 1: Coolant 1 ON Bit 2: Coolant 2 ON Bit 3: Coolant 1 and 2 ON |
| 52230 | \$MCS_M_CODE_ALL_COOLANTS_OFF | 9 | | M code for all coolants OFF |
| 52231 | \$MCS_M_CODE_COOLANT_1_ON | 8 | | M code for coolant 1 ON |
| 52232 | \$MCS_M_CODE_COOLANT_2_ON | 7 | | M code for coolant 2 ON |
| 52233 | \$MCS_M_CODE_COOLANT_1_AND_2_ON | -1 | | M code for coolant 1 + 2 ON |
| 52240 | \$MCS_NAME_TOOL_CHANGE_PROGRAM | " " | "M6" | Tool change program for G code steps |
| 52270 | \$MCS_TM_FUNCTION_MASK | 0H | | Function mask Tool management Bit 0: Create tool on magazine location not allowed. Bit 1: Load/unload disable, if machine is in reset. Bit 2: Load/unload disable on Emergency stop. Bit 3: Load/unload tool to/from spindle is disabled. Bit 4: Loading is executed directly in the spindle. Bit 7: Create tool using the tool number. Bit 8: Fade out Relocate tool. Bit 9: Fade out Position magazine. Bit 10: Reactivate tool using Position magazine. Bit 11: Reactivate tool in all monitoring modes. Bit 12: Fade out Reactivate tool. |
| 52271 | \$MCS_TM_MAG_PLACE_DISTANCE | 70 | | Distance between individual magazine locations. Is used for graphical display of magazine and tools in tool management. |
| 52274 | \$MCS_TM_LOAD_STATION | 0 | | Number of load station = 0: If a query window is on the surface or if only one loading station is available there will be no pop-up window = 1: fixed loading station 1 = 2: fixed loading station 2 |
| 52281 | \$MCS_TOOL_MCODE_FUNC_ON | -1 | | ShopMill only: M code for tool-specific function ON |
| 52282 | \$MCS_TOOL_MCODE_FUNC_OFF | -1 | | M code for tool-specific function OFF If both M commands of a function equal -1, the corresponding field will not be displayed |
| 53230 | \$MAS_SIM_START_POSITION | 0 | X=0 Y=0 Z=300 | Axis position at start of simulation Only adjust with geometry axes |



Notes

Basic settings Technology data

| MD | Identifier | Default | Settings Milling | Description |
|-------|-------------------------------------|---------|------------------|--|
| 54215 | \$SNS_TM_FUNCTION_MASK_SET | 0H | Bit 0 = 1 | Function mask Tool management Bit 0: Diameter display for rotary tools. Bit 1: Default direction of rotation for all turning tools Bit 2: Create tool without suggesting name. Bit 3: Input disable for tool name and tool type in the case of loaded tools. Bit 4: Input disable for loaded tools unless the channel is not in reset. Bit 5: Accrue tool wear entries additively. Bit 6: Entry of tool ID in numerical format. Bit 7: Hide tool monitoring parameters. Bit 8: Diameter display for transverse axis geometry. Bit 9: Diameter display for transverse axis wear. Bit 10: Enable loading/relocation of tool in buffer locations Bit 11: Creation of new tool in gripper locations is disabled Bit 12: Do not unload measuring tools if "Unload all" function is executed. |
| 55200 | \$SCS_MAX_INPUT_FEED_PER_REV | 1 | | Feedrate input upper limit for mm/rev |
| 55201 | \$SCS_MAX_INPUT_FEED_PER_TIME | 10000 | | Feedrate input upper limit for mm/min |
| 55202 | \$SCS_MAX_INPUT_FEED_PER_TOOTH | 1 | | Feedrate input upper limit for mm/tooth |
| 55212 | \$SCS_FUNCTION_MASK_TECH_SELECT | 6H | 7H | Function mask Cross-technology Bit 0: Tool preselection active (ShopMill only) Bit 1: Calculate thread depth from thread pitch Bit 2: Refer to Table for thread diameter and depth |
| 55214 | \$SCS_FUNCTION_MASK_MILL_SET | 5H | | Function mask Milling Bit 0: Default setting - milling cycles with synchronous operation Bit 2: Depth calculation in milling cycles without parameter SC |
| 55216 | \$SCS_FUNCTION_MASK_DRILL_SELECT | 18H | | Function mask Drilling Bit 1: Boring CYCLE86: consider rotation of the tool plane when positioning the spindle Bit 2: Boring CYCLE86: consider swiveled table kinematics when positioning the spindle (tool carrier) Bit 3: Tapping CYCLE84: monitoring machine data 31050 and 31060 of the spindle Bit 4: Tapping CYCLE840: monitoring machine data 31050 and 31060 of the spindle |
| 55220 | \$SCS_FUNCTION_MASK_MILL_TOL_SELECT | 0H | | Function mask High Speed Settings CYCLE832 Bit 0: Unhide technology fields CYCLE832 Bit 1: Orientation tolerance (OTOL) as a tolerance factor, enter it directly |
| 55221 | \$SCS_FUNCTION_MASK_SWIVEL_SELECT | CH | | Function mask Swivel CYCLE800 Bit 0: Display input field "No swivel" Bit 1: Retraction variant Z, Z XY or fixed position = 0: Retract Z or retract Z XY = 1: Retract to fixed position 1 or 2 Bit 2: Allow selection "Deselection" of the swivel data block Bit 3: Show active swivel plane under Swivel in JOG Bit 4: Optimized positioning in basic position (pole position) of the kinematics The settings of the Swivel function mask affect all swivel data records. |



Notes

Setup Milling

Pre-requisite:

Sinumerik Operate is already installed, PLC commissioning has been carried out, the tool management set-up has been completed.

Options:

In order for the required function to be achieved on your machine, the following software options must be available:

- "ShopMill/ShopTurn"
Order Nr. 6FC5800-0AP17-0YB0
- "Residual material detection and machining"
Order Nr. 6FC5800-0AP13-0YB0
- "Simultaneous recording (real-time simulation)"
Order Nr. 6FC5800-0AP22-0YB0
- "3D simulation 1 (finished part)"
Order Nr. 6FC5800-0AP25-0YB0

Configuration of the axes and spindle

Machine axis name

| | |
|--|-------------------|
| MD10000 \$MN_AXCONF_MACHAX_NAME_TAB | Machine axis name |
| Default: X1, Y1, Z1, A1, B1, C1 | Change to: |

Description:

MD10000[0] =X1
MD10000[1] =Y1
MD10000[2] =Z1
MD10000[3] =A1 → SP1
MD10000[4] =B1 → A1
MD10000[5] =C1

Assignment of geometry axis to channel axis

| | |
|---|---|
| MD20050 \$MC_AXCONF_GEOAX_ASSIGN_TAB | Assignment of geometry axis to channel axis |
| Default: 1, 2, 3 | Change to: |

Description:

MD20050[0] = 1
MD20050[1] = 2
MD20050[2] = 3

Geometry axis name in channel

| | |
|---------------------------------------|-------------------------------|
| MD20060 \$MC_AXCONF_GEOAX_NAME_TAB | Geometry axis name in channel |
| Default: X, Y, Z | Change to: |

Description:

MD20060[0] = X
MD20060[1] = Y
MD20060[2] = Z

Machine axis number valid in channel

| | |
|------------------------------------|--------------------------------------|
| MD20070 \$MC_AXCONF_MACHAX_USED | Machine axis number valid in channel |
| Default: 1, 2, 3, 0, 0, 0 | Change to: |

Description:

MD20070[0] =1
MD20070[1] =2
MD20070[2] =3
MD20070[3] =0 → 4
MD20070[4] =0 → 5
MD20070[5] =0 → 6

Channel axis name in channel

| | |
|--|------------------------------|
| MD20080 \$MC_AXCONF_CHANAX_NAME_TAB | Channel axis name in channel |
| Default: X, Y, Z, A, B, C | Change to: |

Description:

MD20080[0] =X
MD20080[1] =Y
MD20080[2] =Z
MD20080[3] =A → SP1
MD20080[4] =B → A
MD20080[5] =C



Notes

Modulo conversion for rotary axis / spindle

| | |
|-------------------------------|---|
| MD30310 \$MA_ROT_IS_MODULO | Modulo conversion for rotary axis / spindle |
| Default: 0 | Change to: |

Description:

AX4: SP1

MD30310 =0 → 1 Modulo-transformation for rotary axis

AX5: A1

MD30310 =0 → 1 Modulo-transformation for rotary axis

AX6: C1

MD30310 =0 → 1 Modulo-transformation for rotary axis

Description:

AX4: SP1

MD30320 =0 → 1 Actual value display Modulo

AX5: A1

MD30320 =0 → 1 Actual value display Modulo

AX6: C1

MD30320 =0 → 1 Actual value display Modulo

Rotary axis / spindle

| | |
|------------------------------|-----------------------|
| MD30300 \$MA_IS_ROT_ACHSE | Rotary axis / spindle |
| Default: 0 | Change to: |

Description:

AX4: SP1

MD30300 =0 → 1 axis is a rotary axis

AX5: A1

MD30300 =0 → 1 axis is a rotary axis

AX6: C1

MD30300 =0 → 1 axis is a rotary axis

Modulo 360 degrees displayed for rotary axis or spindle

| | |
|-----------------------------------|---|
| MD30320 \$MA_DISPLAY_IS_MODULO | Modulo 360 degrees displayed for rotary axis or spindle |
| Default: 0 | Change to: |

Assignment of spindle to machine axis

| | |
|--|---------------------------------------|
| MD35000 \$MA_SPIND_ASSIGN_TO_MACHAX | Assignment of spindle to machine axis |
| Default: 0 | Change to: |


Description:

Definition of the spindle. The spindle is defined if the spindle number is entered into this MD.

AX4: SP1

MD35000 =0 → 1 Assignment of spindle to the machine axis (spindle S1)

Check of the set axes and spindles:



| Machine configuration | | | | | | | |
|-----------------------|------|------------|-----------|------------|------------|---------|--|
| Machine Axis Index | Name | Type | Drive No. | Identifier | Motor Type | Channel | |
| 1 | X1 | Linear | | | | CHAN1 | |
| 2 | Y1 | Linear | | | | CHAN1 | |
| 3 | Z1 | Linear | | | | CHAN1 | |
| 4 | SP1 | Spindle S1 | | | | CHAN1 | |
| 5 | A1 | Rotary | | | | CHAN1 | |
| 6 | C1 | Rotary | | | | CHAN1 | |

Current access level: Manufacturer



Notes

Manufacturer cycles

For the individual matching the following cycles are included in the standard cycle package:

| | |
|----------------|--|
| CUST_800.SPF | Manufacturer's cycle for matching to the functions swivelling plane and tool swivelling (CYCLE800). |
| CUST_832.SPF | Manufacturer's cycle for matching to the function High Speed Settings (CYCLE832). |
| CUST_CLAMP.SPF | Manufacturer's cycle for matching to the function multiple workpiece clamping |
| PROG_EVENT.SPF | Standard cycle for the support of the functionality of: <ul style="list-style-type: none"> • Block search when milling or turning is activated • Block search and swivelling plane • Block search and tool indexing |

Note:

The cycle PROG_EVENT.SPF is a standard Siemens cycle and should not be changed by the manufacturer. For the manufacturer cycles CYCPE1MA.SPF or CYCPE_MA.SPF, the corresponding jump-out markers are prepared at the beginning and at the end of PROG_EVENT.SPF.

At the beginning of the cycle PROG_EVENT

- CYCPE1MA in the directory CMA

At the end of the cycle PROG_EVENT

- CYCPE_MA.SPF in the directory CMA

For these cycles templates are not available. If the CYCPE1MA.SPF and CYCPE_MA.SPF manufacturer cycles are loaded in the NC, the program branches from PROG_EVENT to the manufacturer cycles as appropriate.

Copying the Manufacturer cycles



1. Select the Setup mode for "Commissioning"



2. Press the Softkey "System data".

3. Open the directory NC-data / Cycles / Standard cycles and select the required cycle.



4. Press the Softkey "Copy" and open the directory NC-data / Cycles / Manufacturer's cycles.



5. Press the Softkey "Paste".
Now this cycle is available for individual matching

Setting-up for milling

Matching of the co-ordinate systems to the user interface

Coordinate system position

| | |
|--|----------------------------|
| MD52000 \$MCS_DISP_COORDINATE_ SYSTEM | Coordinate system position |
| Default: 0 | Change to: No change |



Note:

Only the cycles intended for the machine matching commencing with CUST_*.SPF can be copied into the manufacturer or user directory when using the access level "Manufacturer". The cycle "PROG_EVENT.SPF is a standard cycle that can neither be copied nor altered. It is listed here only to indicate the scope for manufacturer-specific matching.



Notes

Selection table of the possible co-ordinate systems



Description:

This MD is used to match the co-ordinate system of the user interface to the co-ordinate system of the machine. In the user interface all help images, the animated graphics, the simulation as well as the input fields with circular direction indication.

The co-ordinate system can take on any of the shown positions.

The typical selection for vertical milling machine is 0 = Pre-setting

Plane selection Milling

| | |
|-----------------------|-------------------------|
| MD52005 | |
| \$MCS_DISP_PLANE_MILL | Plane selection Milling |
| Default: 0 | Change to: No change |

MD52005 = 0

Typical vertical function = G17

Description:


0: Plane selection in the user interface
 This setting makes sense only if the machining plane on the machine can be switched, e.g. by the use of angular milling heads.

17: always G17

18: always G18

19: always G19

The machining planes are specified as shown:







| Plane | Tool axis |
|-------|-----------|
| X/Y | Z G17 |
| Z/X | Y G18 |
| Y/Z | X G19 |



Notes

Continuation MD52005

Example planar milling:



Plane selection by means of the toggle key:
G17 (XY), G18 (ZX), G19 (YZ) or no plane

Technology

| | |
|-----------------------------|--------------|
| MD52200 \$MCS_TECHNOLOGY | Technology |
| Default: 0 | Change to: 2 |

Description:

0: No specific configuration

1: Turning

2: Milling

Please also note MD 52201

\$MCS_TECHNOLOGY_EXTENSION.

Selection of 2 specifies milling as the main technology This means, the Softkeys for drilling and milling will be shown along the lower edge of the screen.



Extended technology

| | |
|---|----------------------|
| MD52201 \$MCS_TECHNOLOGY_EXTEN SION | Extended technology |
| Default: 0 | Change to: No change |

MD52201 presently not applicable:

Meaning of the axes in the channel

| | |
|--------------------------------|------------------------------------|
| MD52206[x] \$MCS_AXIS_USAGE | Meaning of the axes in the channel |
| Default: 0, 0, 0, 0, 0, 0 | Change to: No change |

MD52206[0] =0

MD52206[1] =0

MD52206[2] =0

MD52206[3] =0

MD52206[4] =0

MD52206[5] =0

Description:

No matching specification of the machine datum is required for the sample machine being described here.

Note:

If high-speed extension spindles are used, a 2 must be entered into the respective machine datum of the extension spindle. An extension spindle is not included in the axis configuration used here.



Notes

Axis attributes

| | |
|---------------------------------------|----------------------|
| MD52207[x] \$MCS_AXIS_USAGE_ATTRIB | Axis attributes |
| Default: 0, 0, 0, 0, 0, 0 | Change to: No change |

Description:

- Bit 0: Rotates around the 1st geometry axis (applies to rotary axes)
- Bit 1: Rotates around the 2nd geometry axis (applies to rotary axes)
- Bit 2: Rotates around the 3rd geometry axis (applies to rotary axes)
- Bit 6: Show rotary axis as offset target for measuring
- Bit 7: Offer rotation axis in position pattern

Note:

The Bits 3, 4 and 5 have no meaning in conjunction with ShopMill.

Description:

In case of machines with rotary axes it is possible - in conjunction with the function: "work piece measuring - edge alignment" - to determine the angular correction

For this the following settings are necessary for the rotary axes:

- MD52207[4] axis A = 0 → 81H
- MD52207[5] axis C = 0 → 44H
- Bit 2 = 1: rotates around the 3rd geometry axis
- Bit 6 = 1: Show rotary axis as correction destination for measuring

Example: Measuring zero-point work piece - align edge



Number of actual values with large font

| | |
|---|---|
| MD52010 \$MCS_DISP_NUM_AXIS_BIG_FONT | Number of actual values with large font |
| Default: 3 | Change to: No change |

Description:

Number of actual values with large font, Max. value 31.

| Machine | Position [mm] |
|---------|---------------|
| X1 | 0.000 |
| Y1 | 0.000 |
| Z1 | 0.000 |
| A1 | 0.000° |
| C1 | 0.000° |

Only display spindles in actual values window when in axis mode

| | |
|---------------------------------------|---|
| MD51023 \$MNS_ACT_VALUE_SPIND_MODE | Only display spindles in actual values window when in axis mode |
| Default: 1 | Change to: No change |

Description:

The display of the spindles in the actual value windows can be influenced by means of this. If the datum is set to 1 the spindles will be shown in the actual value window only while they are in the axis mode. The axes are displayed below the geometry and auxiliary axes. Axes that are not in the axis mode are shown as gaps. If set to 0 the spindles will be displayed at all times.



Notes

Function mask display

| | |
|-------------------------------------|-----------------------|
| MD52210 \$MCS_FUNCTION_MASK_DISP | Function mask display |
| Default: 3H | Change to: No change |

MD52210 Bit 0 = 1
MD52210 Bit 1 = 1

Description:

- Bit 0: Meas. sys. for programs always in the base system
- Bit 1: Face view when turning in the school co-ordinate system
- Bit 2: Hide "T,S,M" softkey in Jog area
- Bit 3: Generate automatic end-of-program in MDI (with Softkey "Delete blocks")
- Bit 4: Show follow-on tool in T,F,S window


Bit 3=0: Under MDA the command End-of-program will not be generated automatically after "Block delete".



Bit 3=1: Under MDA the M-command entered in MD 10714 \$M_NO_FCT_EOP will automatically be generated as end-of-program command after "block delete". In this example configuration it is M32.



Bit 4=0: The follow-up tool is not shown in the T;F;S-window



Bit 0: This function is presently not yet available. In a ShopMill program it is always possible to select "mm dimensions" or "inch dimensions" in the program header.



Bit 1: Takes no effect in the Milling technology.

Bit 2=0: The Softkey "T,S,M" is shown in the mode JOG . This setting is in line with the basic setting of Shop-Mill.



Bit 2=1: The Softkey "T,S,M" is hidden in the mode JOG.



Bit 4 = 1 The follow-up tool is shown in the T;F;S-window. This setting makes sense only in conjunction with tool prepare on a machine featuring a double gripper.



Note: Also see the setting of SD 55210 \$SCS_FUNCTION_MASK_TECH_SET, Bit 0 "Tool pre-selection activated"



Notes

Function mask Cross-technology

| | |
|---|------------------------------------|
| MD52212 \$MCS_FUNCTION_MASK_ TECH | Function mask Cross- technology |
| Default: 0H | Change to: 8H |

MD52212 Bit 3 = 0 → 1
MD52212 Bit 5 = 0

Bit 0 and 1 are meaningful for swivelling

Description:

- Bit 0: Enable swivel
- Bit 1: No optimized travel along software limit switches
- Bit 2: Approach logic for step drill (ShopTurn)
- Bit 3: Call block search cycle for ShopMill/ShopTurn
- Bit 4: Approach logic through cycle (ShopTurn)
- Bit 5: Call block search cycle for SERUPRO
- Bit 6: Work offset value ZV cannot be entered (ShopTurn)

Bit 0 and Bit 1 make sense only in conjunction with swivelling. A more detailed description will be found in Module "A111 swivelling".

Bit 2: This Bit is not relevant in the technology Milling . In the ShopMill cycles the longest cutting edge is taken into account when retracting (retraction to the safety level).

Bit 3 = 0

The ShopMill cycle E_S_ASUP is not carried out after block search.

Bit 3 = 1

The ShopMill cycle E_S_ASUP will be carried out after block search. Details regarding this setting are contained in the section "Block search"

Bit 5 = 0

Block search cycle for SERUPRO will not be called up.



The setting = 0 is necessary for single-channel ShopMill machines.

Bit 5 = 1

The standard cycle CY-CLE207 will be called up after Block search with SERUPRO.

The setting of Bit 3 is not effective in this case. The E_S_ASUP will not be called up.

This setting must be used only for multi-channel machines.

Cycle Settings-Drilling

| | |
|--|------------------------|
| MD52216 \$MCS_FUNCTION_MASK_ DRILL | Function mask Drilling |
| Default: 0H | Change to: No change |

Description:

- Bit 0 = 0 Hide input fields Technology
- 1 Show input fields Technology
- CYCLE84 (without compensating chuck)
- Bit 1 = 0 Hide input fields Technology
- 1 Show input fields Technology
- CYCLE840 (with compensating chuck) valid only for ShopMill.



Notes



Continued MD52216

Bit 0 = 0

Technology fields will not be shown in either case:
"with compensating chuck"

Bit 1 = 0

"without compensating chuck"





MD52216 Bit 0 = 1

Technology fields will be shown with the selection "without compensating chuck (Cycle84)"

MD52216 Bit 1 = 1

Technology fields will be shown with the selection "with compensating chuck (Cycle840)"



Function mask Cross-technology

| | |
|---|------------------------------------|
| SD55212 \$SCS_FUNCTION_MASK_ TECH_SET | Function mask Cross- technology |
| Default: 6H | Change to: 7H |

SD55212 Bit 0 = 0 → 1
SD55212 Bit 1 = 1
SD55212 Bit 2 = 1

Description:

Bit 0: Tool pre-selection activated
Bit 1: Evaluate thread depth from metric pitch
Bit 2: Transfer thread diameter and thread depth from table

Bit 0: Tool pre-selection activated
Directly after the exchange has been completed, the tool will be prepared
The generation of the follow-up tool occurs only with Jobshop cycles


Bit 1: Automatic evaluation of the thread depth for metric threads

Bit 2: Transfer thread diameter and thread depth from table.

Bit 1 = 0 The thread depth will not be evaluated automatically

The value for the thread depth "H1" must be entered manually from a table.

Bit 1 = 1 The thread depth will be evaluated from the metric thread pitch.



Notes

SD55212 Continued

Bit 2 = 1 Thread diameter and depth from a table

| Thread milling | |
|----------------|-----------------|
| T | D 1 |
| F | 50.000 mm/min |
| S | 2000.000 rpm |
| Machining | Z0 -> Z1 |
| | RH thread |
| | Internal thread |
| NT | 3 |
| Z1 | 25.000 inc |
| Table | None |
| P | 10.000 mm/rev |
| ∅ | 6.000 |
| H1 | 5.413 |
| DXY | 0.100 inc |
| U | 0.300 |
| αS | 45.000 ° |

| Thread milling | |
|----------------|-----------------|
| T | D 1 |
| F | 50.000 mm/min |
| S | 2000.000 rpm |
| Machining | Z0 -> Z1 |
| | RH thread |
| | Internal thread |
| NT | 3 |
| Z1 | 25.000 inc |
| Table | None |
| P | 8.000 mm/rev |
| ∅ | 6.000 |
| H1 | 4.330 |
| DXY | 0.100 inc |
| U | 0.300 |
| αS | 45.000 ° |

NC/WKS/TEST/ST1

| Thread milling | |
|----------------|-----------------|
| T | D 1 |
| F | 50.000 mm/min |
| S | 2000.000 rpm |
| Machining | Z0 -> Z1 |
| | RH thread |
| | Internal thread |
| NT | 3 |
| Z1 | 25.000 inc |
| Table | None |
| P | 2.000 mm/rev |
| ∅ | 4.122 |
| H1 | 1.083 |
| DXY | 0.100 inc |
| U | 0.300 |
| αS | 45.000 ° |

Only if in the table the column "without" is selected and for P the unit "mm/rev" will the thread depth "H1" in the yellow-backed fields be calculated automatically. These automatically obtained values can be overwritten by the operator. If the thread pitch is entered again, the thread depth will be calculated once more automatically.

Different factors are stored for the internal and external threads:

- Internal threads: 0,5413
- External threads: 0,6134

| Thread milling | |
|----------------|-----------------|
| T | D 1 |
| F | 50.000 mm/min |
| S | 2000.000 rpm |
| Machining | Z0 -> Z1 |
| | RH thread |
| | Internal thread |
| NT | 3 |
| Z1 | 25.000 inc |
| Table | ISO metric |
| Select | M 14 |
| P | 2.000 mm/rev |
| ∅ | 14.000 |
| H1 | 1.083 |
| DXY | 0.100 inc |
| U | 0.300 |
| αS | 45.000 ° |

| Thread milling | |
|----------------|-----------------|
| T | D 1 |
| F | 50.000 mm/min |
| S | 2000.000 rpm |
| Machining | Z0 -> Z1 |
| | RH thread |
| | Internal thread |
| NT | 3 |
| Z1 | 25.000 inc |
| Table | ISO metric |
| Select | M 18 |
| P | 2.500 mm/rev |
| ∅ | 18.000 |
| H1 | 1.353 |
| DXY | 0.100 inc |
| U | 0.300 |
| αS | 45.000 ° |

As soon as the line "Table ISO metric" is selected, the table is activated for the various threads.

The yellow-backed fields for nominal diameters and thread depth H1 will be filled in with tabular values depending on the chosen thread.



Notes

Cycle Settings-Milling

| | |
|---|-----------------------|
| SD55214 \$SCS_FUNCTION_MASK_ MILL_SET | Function mask Milling |
| Default: 5H | Change to: No change |

Description:

- Bit 0: Default setting for milling with synchronous operation
- Bit 1: not assigned
- Bit 2: Depth calculation in milling cycles without parameter SC
- Bit 0 The machining sense (Up-cut/down-cut) can be fixed or selectable via the "toggle" key.

Bit 0 = 1

NC/WKS/TEST/11

Program header

| | |
|--------------------------|--------------|
| Unit of measu | mm |
| Work offset | G54 |
| Blank | Block |
| X0 | 0.000 |
| Y0 | 0.000 |
| X1 | 40.000 inc |
| Y1 | 200.000 inc |
| Z0 | 0.000 |
| Z1 | -100.000 inc |
| PL | G17 (XY) |
| Retraction plane | |
| RP | 99.000 |
| Safety distance | |
| SC | 1.000 |
| Machining sense | Down-cut |
| Retract position pattern | To RP |


Machining sense
Up-cut

Bit 2 = 0

The subdivision of cuts in direction of infeed is calculated including the safety gap SC for the path from Z0+SC to Z1

Bit 2 = 1

The subdivision of cuts in direction of infeed is obtained without the safety gap SC for the path from Z0 to Z1



Note:

The safety gap is specified in the program header.

Function mask Drilling

| | |
|--|------------------------|
| SD55216 \$SCS_FUNCTION_MASK_ DRILL_SET | Function mask Drilling |
| Default: 18H | Change to: No change |

SD55216 Bit 3 = 1

SD55216 Bit 4 = 1



Notes

SD55216 Continued

Description:

- Bit 0: Tapping CYCLE84: Reversal of spindle rotation direction in the cycle
- Bit 1: Boring CYCLE86: Taking into account the rotation of the work piece plane when positioning the spindle
- Bit 2: Boring CYCLE86: Taking into account the indexed table kinematics (tool carrier) when positioning the spindle
- Bit 3: Tapping CYCLE84: (without compensating chuck). Monitoring the machine data 31050[x] and 31060[x] of the spindle
- Bit 4: Tapping CYCLE840: (with compensating chuck). Monitoring the machine data 31050[x] and 31060[x] of the spindle
- Bit 5: Tapping CYCLE84: Evaluation of the point of braking in case of G33

The denominator of the gearbox is contained in MD31050[x] while MD31060[x] contains the numerator. Together the two provide the gear ratio for the spindle. This is required for monitoring the feed obtained from the speed x the pitch.

Description:

- Bit 0: Reversal of the spindle direction of rotation when tapping
This setting is no longer required as from SW 2.6 SP1, since it has been superseded by the NCK.-function.
- Bit 1 = 1: Taking into account the rotation of the tool plane (CYCLE 86)
In the boring cycle, CYCLE86 the spindle is positioned on the parameter SPOS when reaching the boring depth. If SPOS=0 the tool cutting edge points in the positive direction of the 1st axis of the plane (G17 towards X+)

If the setting is varied by using Bit 1 = 1, a rotation about the tool axis (e.g. ROT Z180) will be taken into account for the spindle positioning.
- Bit 2 = 1: Taking into account indexed table kinematics (CYCLE 86)
See description Bit1
With the selection of Bit 2 = 1 an indexed kinematics will be taken into account when positioning the spindle.

Description:

- Bit3 = 1: Tapping CYCLE84: Monitoring the machine data 31050 \$MA_DRIVE_AX_RATIO_DENOM (divider of gearbox ratio) and 31060 \$MA_DRIVE_AX_RATIO_NUMERA (numerator of gearbox ratio) of the spindle for the boring axis

The monitoring is activated only if MD35590 \$MA_PARAMSET_CHANGE_ENABLE = 2
This setting permits a parameter block change by the PLC-interface or by the command SCPARA (servo parameter block programming).
If the monitoring is activated the alarm 61127 [Channel %1:] Block %2 (gear ratio of the tapping axis incorrectly defined) will be set:

- Bit 4 = 1: Similar to Bit3, however, for the cycle CYCLE840
- Bit 5: Calculation of the commencing of braking for G33 CYCLE840)
This function is not available at present.

Cycle Settings

Upper limit feedrate/rev

| | |
|---------------------------------------|--------------------------|
| SD55200 \$SCS_MAX_INP_FEED_PER_REV | Upper limit feedrate/rev |
| Default: 1 mm/U | Change to: No change |

Description:

Upper limit for the selection of the federate/rev

Upper limit feedrate/min

| | |
|--|--------------------------|
| SD55201 \$SCS_MAX_INP_FEED_PER_TIME | Upper limit feedrate/min |
| Default: 10000 mm/min | Change to: No change |

Description:

Upper limit for the input of the feedrate in mm/min



Notes

Upper limit feedrate/tooth

| | |
|---|----------------------------|
| SD55202 \$SCS_MAX_INP_FEED_PER_TOOTH | Upper limit feedrate/tooth |
| Default: 1 mm | Change to: No change |

Description:

Upper limit for the selection of the feedrate/tooth

Setting up the tool list

These settings are applicable only to JobShop programs

Enable fast M functions

| | |
|---------------------------------------|-------------------------|
| MD52229 \$MCS_ENABLE_QUICK_M_CODES | Enable fast M functions |
| Default: 0H | Change to: No change |

Description:

- Bit 0: Coolant OFF
- Bit 1: Coolant 1 ON
- Bit 2: Coolant 2 ON
- Bit 3: Coolant 1 and 2 ON

This MD is used to declare the commands used for the coolant control (see MD52230 - MD52233) as being fast M-commands (M=QU...). In case of fast commands the program progress continues without waiting for the acknowledgement of the M-command by the PLC.

In the tool list there are input fields for coolant 1 and coolant 2 for each tool. The select key can be used to toggle the function "coolant ON/OFF". The respective M-functions are put out if the tool is changed by means of the part-program, The M-commands will not be put out if the tool is exchanged by means of the T,S,M mask.

| Loc. | Type | Tool name | ST | D | Length | ø | Tip angle | M |
|------|------|----------------|----|---|--------|--------|-----------|-------------------------------------|
| | | TWIST_DRILL_8 | 1 | 1 | 8.000 | 8.000 | 118.0 | <input checked="" type="checkbox"/> |
| 1 | | END_MILL_10 | 1 | 1 | 10.000 | 10.000 | 4 | <input checked="" type="checkbox"/> |
| 2 | | END_MILL_20 | 1 | 1 | 8.000 | 20.000 | 4 | <input checked="" type="checkbox"/> |
| 4 | | TWIST_DRILL_12 | 1 | 1 | 8.000 | 12.000 | 118.0 | <input checked="" type="checkbox"/> |
| 5 | | TAP_M10 | 1 | 1 | 8.000 | 10.000 | 3.000 | <input checked="" type="checkbox"/> |

M code for all coolants OFF

| | |
|--|-----------------------------|
| MD52230 \$MCS_M_CODE_ALL_COOLANTS_OFF | M code for all coolants OFF |
| Default: 9 | Change to: No change |

Description:

M-Code for all coolant OFF

M code for coolant 1 ON

| | |
|--------------------------------------|-------------------------|
| MD52231 \$MCS_M_CODE_COOLANT_1_ON | M code for coolant 1 ON |
| Default: 8 | Change to: No change |

Description:

M-Code for coolant 1 ON



Notes

M code for coolant 2 ON

| | |
|--------------------------------------|-------------------------|
| MD52232 \$MCS_M_CODE_COOLANT_2_ON | M code for coolant 2 ON |
| Default: 7 | Change to: No change |

Description:

M-Code for coolant 2 ON

M code for both coolants ON

| | |
|--|-----------------------------|
| MD52233 \$MCS_M_CODE_COOLANT_1_AND_2_ON | M code for both coolants ON |
| Default: -1 | Change to: No change |

Description:

M-Code for Coolant 1 + 2 ON

Already defined: M8 = Coolant 1 ON
M7 = Coolant 2 ON

If in the JobShop tool list both coolants (coolant 1 and coolant 2) have been selected, the following M-command is generated:

-1: M-command for coolant 1 on (setting of MD52231) and M-command for coolant 2 on (setting of MD52232)

>0: the M-command selected in this MD.

A separate M-command for both coolants is to be used if the M-commands for coolant 1 and coolant 2 are grouped in one M-commands group, however both coolants are to be activated after a block search.

M code for tool-specific function ON

| | |
|---------------------------------------|--------------------------------------|
| MD52281[x] \$MCS_TOL_MCODE_FUNC_ON | M code for tool-specific function ON |
| Default: -1 | Change to: No change |

Description:

In MD52281[0] - [3] ON and in MD52282[0] - [3] OFF up to 4 additional columns for tool-specific functions can be activated in the tool list. These can then be selected in the columns M1- M4 (see Screenshot "Tool list" on the following page).

The screenshot shows a 'Tool list' table with columns: Loc., Type, Tool name, ST, D, length, ø, H, and four M-code columns (M1, M2, M3, M4). Tools listed include TWIST_DRILL_8, END_MILL_10, END_MILL_20, TWIST_DRILL_12, and TAP_M10. The M1-M4 columns contain checkboxes for selecting tool-specific functions.

Description:

M-Code for tool-specific function ON

The value -1 means that the M-function will not be put out. If both M-commands of a function = -1, the associated field in the surface will not be shown.



Notes

M code for tool specific function OFF

| | |
|---|---------------------------------------|
| MD52282[x] \$MCS_TOOL_MCODE_FUNC _OFF | M code for tool-specific function OFF |
| Default: -1 | Change to: No change |

Description:

M-Code for tool-specific function ON
The value -1 means that the M-function will not be put out. If both M-commands of a function = -1, the associated field in the surface will not be shown.

- Bit 6: reserved
- Bit 7: Create tool by means of the T-number.
The T-number of the tool must be entered when a new tool is created.
- Bit 8: Hide 'Re-locate tool'
The function 'Re-locate tool' is suppressed on the user interface.
- Bit 9: Hide 'Magazine positioning'
The function 'magazine positioning' is suppressed on the user interface.
- Bit 10: Re-activation of tool using magazine positioning
Before re-activation the tool is located on the loading position.
- Bit 11: Re-activating the tool in all monitoring modes.
When re-activating a tool, all monitoring modes for this tool released in the NC will also be re-activated; i.e. also those monitoring modes that are not selected for the respective tool, but which are dormant in the background.
- Bit 12: Hide 'Tool re-activation'
The function "Tool re-activating" is suppressed on the user interface.

Function mask Tool management

| | |
|-----------------------------------|-------------------------------|
| MD52270 \$MCS_TM_FUNKTION_MASK | Function mask Tool management |
| Default: 0H | Change to: 4H |

Description:

- Bit 0: Create tool on a magazine location not permitted.
Tools can only be created outside the magazine.
- Bit 1: Loading/unloading is not possible while the machine is not in Reset.
Tools can only be loaded or unloaded if the respective channel is at rest.
- Bit 2: Loading/unloading locked during emergency OFF
Tools can only be loaded or unloaded if the Emergency OFF is not activated.
- Bit 3: Loading/unloading tools to/from spindle disabled.
Tools cannot be loaded to or unloaded from the spindle.
- Bit 4: Loading takes place in the spindle directly.
The tools are only loaded exclusively in the spindle.
- Bit 5: reserved

Notes:

This MD must be matched to the circumstances of the machine. By hiding those functions on the user interface that are not applicable to the machine, the PLC can be spared unnecessary actions to prevent operation errors.

Bit 7: Create tool using the T-number
This function is intended for machines with tool management but without magazine configuration. The default setting must not be changed.



Notes

Load station Tool management

| | |
|--|------------------------------|
| MD52274 \$MCS_TM_TOOL_LOAD_ STATION | Load station Tool management |
| Default: 0 | Change to: No change |

MD52274 = 0 → max. 16

Description:

If only one loading station is configured: The setting = 0

= 0: There will be no pop-up window.



If more than 1 loading station is configured, you can select between

= 0: A query window appears on the surface to select the loading point.

= 1: fixed loading station 1, the window does not appear

= 2: fixed loading station 2, the window does not appear

The following screenshots show a configuration with two loading stations and the setting MD52274 = 0.



Acknowledge the selection made with OK



Function mask Tool management

| | |
|---------------------------------------|-------------------------------|
| SD54215 \$SNS_TM_FUNCTION_MASK SET | Function mask Tool management |
| Default: 0H | Change to: 1H |

Bit 0 = 0 → 1 Diameter readout for rotating tools

Description:

Bit 0: Diameter readout for rotating tools

It is not the radius value, but the diameter value that is shown for rotating tools.

Bit 1: Default direction of rotation for all turning tools is M4
When turning tools are created, the direction of rotation is preset to M4.


Bit 2: Creating tools without assigning a name
When creating a new tool the input field for the tool name remains empty.

Bit 3: Input interlock for tool name and tool type for loaded tools
Tool name and tool type cannot be changed for loaded tools.

Bit 5: Evaluation of tool wear inputs additively
The input of wear data will be added to any existing wear values.

Bit 6: Numeric input of the tool identification
No name will be assigned to a new tool being created. Only numerical characters are permitted .

Bit 7: Hiding the tool monitoring parameter
The tool monitoring parameter will not be shown on the user interface.



Notes

Continued SD54215

Description:

- Bit 8: Diameter readout for transverse axis - geometry
The geometry value of the transverse axis is shown as a diameter value.
- Bit 9: Diameter readout for transverse axis - wear
The wear value of the transverse axis is shown as diameter value.
- Bit 10: Release of Tool loading / Tool re-location to buffer station
The magazine number can be entered in the loading dialog. This permits access to the buffer station using the magazine number 9998.
- Bit 11: The creation of new tools in the gripper locations is blocked.

Bit 0 = 0 permanent radius readout for all tools

| Loc. | Type | Tool name | ST | D | Length | Radius | Tip angle | | | | M |
|------|------|----------------|----|---|--------|--------|-----------|---|--------------------------|--------------------------|--------------------------|
| | | TWIST_DRILL_8 | 1 | 1 | 0.000 | 4.000 | 118.0 | | <input type="checkbox"/> | <input type="checkbox"/> | 1 |
| 1 | | END_MILL_10 | 1 | 1 | 10.000 | 5.000 | | 4 | | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | | END_MILL_20 | 1 | 1 | 0.000 | 10.000 | | 4 | | <input type="checkbox"/> | <input type="checkbox"/> |
| 4 | | TWIST_DRILL_12 | 1 | 1 | 0.000 | 6.000 | 118.0 | | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5 | | TAP_M10 | 1 | 1 | 0.000 | 5.000 | 3.000 | | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6 | | | | | | | | | | | |
| 7 | | | | | | | | | | | |
| 8 | | | | | | | | | | | |
| 9 | | | | | | | | | | | |
| 10 | | | | | | | | | | | |
| 11 | | | | | | | | | | | |
| 12 | | | | | | | | | | | |
| 13 | | | | | | | | | | | |
| 14 | | | | | | | | | | | |
| 15 | | | | | | | | | | | |
| 16 | | | | | | | | | | | |
| 17 | | | | | | | | | | | |

Bit 0 = 1 Diameter readout for rotating tools

| Loc. | Type | Tool name | ST | D | Length | ∅ | Tip angle | | | | M |
|------|------|----------------|----|---|--------|--------|-----------|--|--------------------------|--------------------------|--------------------------|
| | | TWIST_DRILL_8 | 1 | 1 | 0.000 | 8.000 | 118.0 | | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 1 | | END_MILL_10 | 1 | 1 | 10.000 | 10.000 | 4 | | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | | END_MILL_20 | 1 | 1 | 0.000 | 20.000 | 4 | | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4 | | TWIST_DRILL_12 | 1 | 1 | 0.000 | 12.000 | 118.0 | | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5 | | TAP_M10 | 1 | 1 | 0.000 | 10.000 | 3.000 | | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6 | | | | | | | | | | | |
| 7 | | | | | | | | | | | |
| 8 | | | | | | | | | | | |
| 9 | | | | | | | | | | | |
| 10 | | | | | | | | | | | |
| 11 | | | | | | | | | | | |
| 12 | | | | | | | | | | | |
| 13 | | | | | | | | | | | |
| 14 | | | | | | | | | | | |
| 15 | | | | | | | | | | | |
| 16 | | | | | | | | | | | |
| 17 | | | | | | | | | | | |

Bit10 = 1 Release of Tool relocation to buffer station

| Loc. | Type | Tool name | ST | D | Length | ∅ | Tip angle | | | | M |
|------|------|---------------|----|---|--------|-------|-----------|--|--------------------------|--------------------------|--------------------------|
| 13 | | | | | | | | | | | |
| 14 | | | | | | | | | | | |
| 15 | | | | | | | | | | | |
| 16 | | | | | | | | | | | |
| 17 | | | | | | | | | | | |
| 18 | | | | | | | | | | | |
| 19 | | | | | | | | | | | |
| 20 | | | | | | | | | | | |
| 21 | | | | | | | | | | | |
| 22 | | | | | | | | | | | |
| 23 | | | | | | | | | | | |
| 24 | | | | | | | | | | | |
| 25 | | | | | | | | | | | |
| 26 | | | | | | | | | | | |
| 27 | | | | | | | | | | | |
| 28 | | | | | | | | | | | |
| 29 | | | | | | | | | | | |
| 30 | | | | | | | | | | | |
| | | TWIST_DRILL_8 | 1 | 1 | 0.000 | 8.000 | 118.0 | | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Load on ...

.. magazine 9998 Locat. 1




Notes

Continued SD54215

The locations 1 = spindle, 2 = gripper 1 and 3 = gripper 2 can be loaded directly by means of the magazine number 9998. In the tool list these are the uppermost three lines without numbering. In the shown example the "TWIST_DRILL_8" is loaded in the spindle.

| Tool list | | | | | | | | | | Magazine | | |
|-----------|------|---------------|----|---|--------|-------|-----------|--|--|----------|---|---|
| Loc. | Type | Tool name | ST | D | Length | ∅ | Tip angle | | | M | M | M |
| | | | | | | | | | | 1 | 2 | 3 |
| 1 | | TWIST_DRILL_8 | 1 | 1 | 8.000 | 8.000 | 118.0 | | | | | |

Checking the tool management



Marked tools can be unloaded. As soon as the cursor is moved to a free magazine location the Softkey "New tool" appears for the creation of a new tool.

The screenshot shows a multi-line tool list. The first three lines are for magazine locations 1, 2, and 3. The rest of the list contains tools like END_MILL_2, END_MILL_10, END_MILL_20, TWIST_DRILL_8, TWIST_DRILL_12, TAP_M10, FACING_TOOL, TAP_M16, and END_MILL_6. At the bottom, a 'New tool' softkey is highlighted with a red box and an arrow.

By horizontal scrolling the fields for all tool-specific M-functions M1 ... M4 appear.

The diagram shows a grid of tool-specific M-function fields (M1-M4) for various tool types. An arrow points to the 'New tool' softkey, which opens a selection list titled 'New tool - favorites'. The list includes various tool types and their identifiers, such as '120 - End mill', '140 - Facing tool', '200 - Twist drill', etc.

Basic settings

Reset-defiant settings

Definition of basic control settings after reset/PP end

| | |
|---------------------------------|---|
| MD20110 \$MC_RESET_MODE_MASK | Definition of basic control settings after reset/PP end |
| Default: 1H | Change to: 4041H |

| | | | | | | | | | | | | | | | |
|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|
| 31 | 30 | 29 | 28 | 27 | 26 | 25 | 24 | 23 | 22 | 21 | 20 | 19 | 18 | 17 | 16 |
| 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 0 | | | | 0 | | | | 0 | | | | | | | |

| | | | | | | | | | | | | | | | | |
|----|----|----|----|----|----|---|---|---|---|---|---|---|---|---|---|-----------|
| 15 | 14 | 13 | 12 | 11 | 10 | 9 | 8 | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 | Bit |
| 0 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 0 | 0 | 1 | Bit-masks |
| 4 | | | | 0 | | | | 4 | | | | 1 | | | | Hex |

The various types of tools are shown in the selection list.



Notes

Continued MD20110**Bit 0 = 1****Bit 6 = 0 → 1****Bit 14 = 0 → 1****Description:**

Determination of the basic control settings after booting and reset/End-of-part-program with respect to the G-codes (especially the current plane and selectable zero-point offset), tool length and transformation by the setting of the following bits:

- Bit 0: Reset mode
- Bit 1: Suppression of aux. function output on tool selection
- Bit 2: Selection of the reset response after power ON; e.g. the tool offset
- Bit 3: Selection of the reset response after the end of the test mode in respect of active tool offsets.
- Bit 4: Reserved
- Bit 5: Reserved
- Bit 6: Reset response "Active tool length offset"
- Bit 7: Reset response "Active kinematics transformation"
- Bit 8: Reset response "Coupled-motion axes"
- Bit 9: Reset response "Tangential correction"
- Bit 10: Reset response "Synchronous spindle"
- Bit 11: Reset response "Rotational feed"
- Bit 12: Reset response "Geo-axis replacement"
- Bit 13: Reset response "Master value coupling"
- Bit 14: Reset response "Initial frames"
- Bit 15: Reset response "Electronic gearbox"

- G-Codes as per \$MC_GCODE_RESET_VALUES
- Tool length offset not active
- Transformation not active
- No coupled-motion groupings active
- No tangential offsets active
- No master value couplings active
- No axial rotational feedrate active
- Path rotational feedrate with master spindle (Default)

Bit 0 (LSB) = 1:

Initial setting after booting:

- G-Codes as per \$MC_GCODE_RESET_VALUES
- Tool length offset active as per \$MC_TOOL_RESET_VALUE, \$MC_CUTTING_EDGE_RESET_VALUE and \$MC_SUMCORR_RESET_VALUE
- Transformation active per \$MC_TRAFO_RESET_VALUE
- Geo axis replacement as per \$MC_GEOAX_CHANGE_RESET
- No coupled-motion groupings active
- No tangential correction active

Initial setting after reset or after end-of-part-program:

Depending on the setting of \$MC_GCODE_RESET_MODE the current settings for the G-groups will be retained or set to the initial values stored in \$MC_GCODE_RESET_VALUES.

Description:

Bit 16: Reset response "Master spindle"

Bit 17: Reset response "Master tool holder"

Bit 18: Reset response "Reference axis for G96/G961/G962"

Bit 19: Reserved "variable SW limit switches disabled"

The Bits 4 to 11, 16 and 17 are only evaluated if Bit 0 = 1

Meaning of the individual Bits:

Bit 0 (LSB) = 0:

Initial setting after booting:

- G-Codes as per \$MC_GCODE_RESET_VALUES
- Tool length offset not active
- Transformation not active
- no coupled axes groupings active
- no tangential correction active
- no axial rotational feed active
- path rotational feed with master spindle (Default)

Initial setting after Reset or after end-of-part-program :

The current settings will be retained.

With the next part-program Start the following Initial settings will become active:

Description:

Initial setting after Reset or after end-of-part program:

Depending on \$MC_RESET_MODE_MASK Bit 6 to 7 the current settings for

- Tool length offset
- Transformation

will either be retained or changed to the initial settings as stored in the MDs.

Depending on Bit 8 and 9 the current settings of coupled motion axes or tangentially corrected axes will either be retained or switched OFF.

Projected synchronous spindle coupling:

The coupling will be un-selected depending on the setting of \$MC_COUPLE_RESET_MODE_1.

Non-projected synchronous spindle coupling:

Depending on Bit 10 the coupling will either be switched OFF or retained.

Depending on Bit 14 the initial frame will be retained or un-selected.

Note:

The setting of Bit 0 = 1 must be set for JobShop-uses, such that the settings of the Bits 4 to 11, 16 and 17 can be evaluated.



Notes

Continued MD20110**Bit 1 = 0:**

Auxiliary function output (D,T,M,) to the PLC when selecting tools according to the MDs \$MC_TOOL_RESET_VALUE, \$MC_CUTTING_EDGE_RESET_VALUE, \$MC_TOOL_PRESEL_RESET_VALUE and \$MC_TOOL_CHANGE_MODE.

T, M will not generally be put out as auxiliary functions if the magazine management is activated.
The function utilizes its own communication in order to put out T, M also - among others - to the PLC.

Bit 1 = 1:

Suppress auxiliary function output to the PLC when selecting tools.

T, M will not generally be put out as auxiliary functions if the tool and magazine management is activated.

Bit 2 = 0 :

If tool and magazine management is not active:

- No tool correction after power On is active. Active and programmed T depend on the additional settings of the machine datum (Bits 0, 6).

If the tool or the magazine management are not active:
- not relevant

Bit 3 = 1:

On any meaning only if the tool management is active:

- End of the test mode: "Retain the current setting for the active tool length offset" (Bits 0 and 6 are set) refers to the program that was active before switching ON the test mode.
(Generally speaking the tool in the spindle is the active tool if the tool management is activated. Exception only for \$MC_CUTTING_EDGE_DEFAULT = -2.)

Bit 4 = 0: Reserved

Bit 4 = 1: Reserved

Bit 5 = 0: Reserved

Bit 5 = 1: Reserved

Bit 6 = 0:

Initial setting for the active tool length offset after Reset/End-of-part program as per \$MC_TOOL_RESET_VALUE, \$MC_CUTTING_EDGE_RESET_VALUE, \$MC_USEKT_RESET_VALUE and \$MC_SUMCORR_RESET_VALUE.
Is \$MC_TOOL_CHANGE_MODE = 1, the tool specified by \$MC_TOOL_PRESEL_RESET_VALUE is additionally pre-selected.

If the tool and/or magazine management is active, it is not the datum \$MC_TOOL_RESET_VALUE that is used, instead \$MC_TOOL_RESET_NAME will be used.

Description:**Bit 2 = 1 :**

If the tool and/or magazine management is not activated:
- If both Bits 0 and 6 both have the value = 1 (0x41), then the tool offsets of the last tool to be active in NCK after the first reset after Power ON will be active.
(The value of the programmed tool depends on the value of the machine datum \$MC_TOOL_PRESEL_RESET_VALUE.)

Caution:

NCK is not aware of the conditions at the machine.

Not relevant, if the tool and or the magazine management is active.

Bit 3 = 0:

With or without tool management:

- End of the test mode: "Retain the current setting for the active tool length offset" (Bits 0 and 6 are set) refers to the program that was active before switching ON the test mode.

Description:**Bit 6 = 1:**

The current setting for the active tool length offset remains in force after reset/End-of-part-program.
If the tool and/or magazine management is active, that tool will be selected which is presently loaded in the master spindle (generally = master tool holder).
If the tool in the master spindle happens to be blocked, the "blocked"-status will be ignored. .

However, it must be remembered that after the end of program or a program interruption either the last programmed value for the master spindle or master tool holder, or the value specified by \$MC_SPIND_DEF_MASTER_SPIND or \$MC_TOOL_MANAGEMENT_TOOLHOLDER will determine the master spindle or the master tool holder.
(The selection is made by Bit 16 or Bit 17.)

A special case is \$MC_CUTTING_EDGE_DEFAULT = -2:
If a tool has been changed on the spindle, but no new correction D has been programmed, then the previous tool is still active in the NCK.
If an interruption takes place in this state, - e.g. by pressing the reset key, the correction will be specified by the lowest D-number of the tool in the master spindle.



Notes

MD20110 continued

Note:

The setting Bit 6=1 is necessary to ensure that after a reset/End-of-part-program the previously programmed tool and the previously programmed cutting edge remains activated (for instance, if the tool was changed via the T,S,M-mask) and if for example the JobShop-functions in the mode of operation JOG "Zero point work piece" or "Tool measurement" can be carried out with this tool.

Bit 7 = 0:

Initial setting for active transformation after Reset/End-of-part-program as per \$MC_TRAFO_RESET_VALUE.

Bit 7 = 1:

The current setting for the active transformation remains operative after Reset/End-of-part-program.

Bit 8 = 0:

Coupled-motion groupings will be de-activated after Reset/End-of-part-program.

Bit 8 = 1:

Coupled-motion groupings remain active after Reset/End-of-part-program.

Description:**Bit 9 = 0:**

Tangential correction will be switched OFF with Reset/End-of-part-program.

Bit 9 = 1:

Tangential correction remains activated after Reset/End-of-part program.

Bit 10 = 0:

Non-projected synchronous spindle coupling will be switched OFF after Reset/End-of-part-program.

Bit 10 = 1:

on-projected synchronous spindle coupling remains activated after Reset/End-of-part-program.

Bit 11 = 0:

With Reset/End-of-part-program the setting datum \$SA_ASSIGN_FEED_PER_REV_SOURCE of all non-active axes/spindles will be set to =0, i.e feed no longer takes place with rotational feedrate and the setting for path and synchronous axes will be reset to the master spindle (Default)

Bit 11 = 1:

The current setting for the rotational feedrate remains activated after a Reset/End-of-part-program. When a part program is started, the setting datum \$SA_ASSIGN_FEED_PER_REV_SOURCE will be reset to 0 for all non-active axes/spindles, i.e. feed no longer takes place with rotational feedrate and the setting for path and synchronous axes will be reset to the master spindle (Default).

Bit 12 = 0:

If the machine datum \$MC_GEOAX_CHANGE_RESET is set, a changed geometry axis attribution will be cancelled with reset or with end-of-part program. The initial setting specified in the machine data for the geometry axis attribution is activated.

Bit 12 = 1:

A changed geometry axis attribution remains activated after a Reset/End-of-part-program.

Bit 13 = 0:

Master value couplings are cancelled with Reset/End-of-part-program.

Bit 13 = 1:

Master value couplings remain active after Reset/End-of-part-program.

Description:**Bit 14 = 0:**

The basic frame is cancelled

Bit 14 = 1:

The current setting for the basic frame is retained.

Note:

The setting Bit 14 = 1 is necessary to retain the channel-specific basic work offset (WO), which was activated with G500, after a Reset/End-of-part-program. After activation of the basic WO (JOG-T,S,M-mask - Work offset - basic reference) the values in the Work offset base are transferred to the Total basic WO and then from there to be transferred for activation also to the Total WO.



Notes

Continued MD20110

| Work offset - basic [mm] | | | | | | |
|--------------------------|-------|-------|---------|-------|-------|--|
| | X | Y | Z | A1 | C1 | |
| 1. Channel Basic WJ0 | 0.000 | 0.000 | 100.000 | 0.000 | 0.000 | |
| Fine | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | |



| Work offset - Overview [mm] | | | | | | |
|-----------------------------|-------|-------|---------|-------|-------|--|
| | X | Y | Z | A1 | C1 | |
| DRF | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | |
| Rotary table ref. | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | |
| Basic reference | 0.000 | 0.000 | 50.000 | 0.000 | 0.000 | |
| Total basic WJ0 | 0.000 | 0.000 | 100.000 | 0.000 | 0.000 | |
| G500 | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | |
| Tool reference | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | |
| Workpiece ref. | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | |
| Programmed WJ0 | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | |
| Cycle reference | 0.000 | 0.000 | 0.000 | 0.000 | 0.000 | |
| Total WJ0 | 0.000 | 0.000 | 150.000 | 0.000 | 0.000 | |

Bit 15 = 0:

Active electronic gearboxes remain activated after Reset/End-of-part-program.

Bit 15 = 1:

Active electronic gearboxes are cancelled with Reset/End-of-part-program.

Bit 16 = 0:

Initial setting for the master spindle as per \$MC_SPIND_DEF_MASTER_SPIND.

Bit 16 = 1:

The current setting of the master spindle (SETMS) is retained. This Bit in case of \$MC_TOOL_MANAGEMENT_TOOLHOLDER = 0 has also an effect on the response of Bit 6.

Note:

The setting of Bit 16 is not applicable to ShopMill.

Description:

Bit 17 = 0:

Initial setting for the master tool holder as per \$MC_TOOL_MANAGEMENT_TOOLHOLDER.

Bit 17 = 1:

The current setting for the master tool holder (SETMTH) is retained. (Bit17 is of importance only if the tool or magazine management is active and if \$MC_TOOL_MANAGEMENT_TOOLHOLDER > 0. Otherwise Bit 16 applies to the setting for the master spindle if the tool or magazine management is active. This Bit also has an effect on Bit 6.

Bit 18 = 0:

Reference axis for G96/G961/G962 as per MD 20100: \$MC_DIAMETER_AX_DEF. If SCC is used for an own spindle reset Bit 18 = 1 is recommended (see also MD 20112: \$MC_START_MODE_MASK, Bit 18).

Bit 18 = 1:

The reference axis for G96/G961/G962 is retained.

Bit 19: Reserved!

The previously described settings in MD20110 correspond to the further MD-settings in:

- MD20120 \$MC_TOOL_RESET_VALUE
- MD20130 \$MC_CUTTING_EDGE_RESET_VALUE
- MD20150 \$MC_GCODE_RESET_VALUES
- MD20152 \$MC_GCODE_RESET_MODE
- MD20140 \$MC_TRAFO_RESET_VALUE
- MD20112 \$MC_START_MODE_MASK
- MD20121 \$MC_TOOL_PRESEL_RESET_VALUE
- MD20118 \$MC_GEOAX_CHANGE_RESET



Notes

Tool edge with length compensation during runup (reset/end of part program)

Corresponds to:
MD20110 \$MC_RESET_MODE_MASK
MD20112 \$MC_START_MODE_MASK

| | |
|--|---|
| MD20130 \$MC_CUTTING_EDGE_RESET_VALUE | Tool edge with length compens. during runup (reset/end of pp) |
| Default: 0 | Change to: 1 |

Note:

This setting is necessary to ensure that after a reset/End-of-part-program the previously programmed tool and the previously programmed cutting edge remains activated (for instance, if the tool was changed via the T,S,M-mask) and if for example the JobShop-functions in the mode of operation JOG "Zero point work piece" or "Tool measurement" can be carried out with this tool.

MD20130 = 0 → 1

Description:

Specification of the cutting edge, which depending on MD20110 \$MC_RESET_MODE_MASK and after part program Start depending on MD20112 \$MC_START_MODE_MASK is used to select the tool length offset after booting and after Reset /End-of-part-program.

With active tool management and with Bit 0 and Bit 6 set in MD20110 \$MC_RESET_MODE_MASK at selection, the last offset of the tool active at power OFF (as a rule the tool in the spindle) is effective after booting.

Initial setting of G groups

| | |
|------------------------------------|-----------------------------|
| MD20150 \$MC_GCODE_RESET_VALUES | Initial setting of G groups |
| Default: | Change to: No change |

MD20150[15] = 1 → 3 (CFIN)
MD20150[21] = 1 → 2 (CUT2DF)
MD20150[41] = 1 (TCOABS)
MD20150[51] = 1 (PAROTOF)
MD20150[52] = 1 (TOROTOF)

Description:

Specification of the G-Codes, which after booting and Reset/End-of-part program are activated depending on MD20110 \$MC_RESET_MODE_MASK and MD20152 \$MC_GCODE_RESET_MODE as well as after part program Start depending on MD20112 \$MC_START_MODE_MASK.

As a default value the index of the G-codes in the respective groups must be stated.

Description:

| Denomination | Group | Standard value for 840D sl |
|-------------------------------|-----------|----------------------------|
| GCODE_RESET_VALUES[0] | 1 | 2 (G1) |
| GCODE_RESET_VALUES[1] | 2 | 0 (inactive) |
| GCODE_RESET_VALUES[2] | 3 | 0 (inactive) |
| GCODE_RESET_VALUES[3] | 4 | 1 (STARTFIFO) |
| GCODE_RESET_VALUES[4] | 5 | 0 (inactive) |
| GCODE_RESET_VALUES[5] | 6 | 1 (G17) |
| GCODE_RESET_VALUES[6] | 7 | 1 (G40) |
| GCODE_RESET_VALUES[7] | 8 | 1 (G500) |
| GCODE_RESET_VALUES[8] | 9 | 0 (inactive) |
| GCODE_RESET_VALUES[9] | 10 | 1 (G60) |
| GCODE_RESET_VALUES[10] | 11 | 0 (inactive) |
| GCODE_RESET_VALUES[11] | 12 | 1 (G601) |
| GCODE_RESET_VALUES[12] | 13 | 2 (G71) |
| GCODE_RESET_VALUES[13] | 14 | 1 (G90) |
| GCODE_RESET_VALUES[14] | 15 | 2 (G94) |
| GCODE_RESET_VALUES[15] | 16 | 1 (CFC) |
| GCODE_RESET_VALUES[16] | 17 | 1 (NORM) |
| GCODE_RESET_VALUES[17] | 18 | 1 (G450) |
| GCODE_RESET_VALUES[18] | 19 | 1 (BNAT) |
| GCODE_RESET_VALUES[19] | 20 | 1 (ENAT) |
| GCODE_RESET_VALUES[20] | 21 | 1 (BRISK) |



Notes

Continued MD20150

Description:

| Denomination | Group | Standard value for 840D sl |
|-------------------------------|-----------|----------------------------|
| GCODE_RESET_VALUES[21] | 22 | 1 (CUT2D) |
| GCODE_RESET_VALUES[22] | 23 | 1 (CDOF) |
| GCODE_RESET_VALUES[23] | 24 | 1 (FFWOF) |
| GCODE_RESET_VALUES[24] | 25 | 1 (ORIWKS) |
| GCODE_RESET_VALUES[25] | 26 | 2 (RMI) |
| GCODE_RESET_VALUES[26] | 27 | 1 (ORIC) |
| GCODE_RESET_VALUES[27] | 28 | 1 (WALIMON) |
| GCODE_RESET_VALUES[28] | 29 | 1 (DIAMOF) |
| GCODE_RESET_VALUES[29] | 30 | 1 (COMPOF) |
| GCODE_RESET_VALUES[30] | 31 | 1 (G810) |
| GCODE_RESET_VALUES[31] | 32 | 1 (G820) |
| GCODE_RESET_VALUES[32] | 33 | 1 (FTOCOF) |
| GCODE_RESET_VALUES[33] | 34 | 1 (OSOF) |
| GCODE_RESET_VALUES[34] | 35 | 1 (SPOF) |
| GCODE_RESET_VALUES[35] | 36 | 1 (PDELAYON) |
| GCODE_RESET_VALUES[36] | 37 | 1 (FNORM) |
| GCODE_RESET_VALUES[37] | 38 | 1 (SPIF1) |
| GCODE_RESET_VALUES[38] | 39 | 1 (CPRECOF) |
| GCODE_RESET_VALUES[39] | 40 | 1 (CUTCONOF) |
| GCODE_RESET_VALUES[40] | 41 | 1 (LFOF) |

| | | |
|-------------------------------|-----------|--------------------------|
| GCODE_RESET_VALUES[41] | 42 | 1 (TCOABS) |
| GCODE_RESET_VALUES[42] | 43 | 1 (G140) |
| GCODE_RESET_VALUES[43] | 44 | 1 (G340) |
| GCODE_RESET_VALUES[44] | 45 | 1 (SPATH) |
| GCODE_RESET_VALUES[45] | 46 | 1 (LFTXT) |
| GCODE_RESET_VALUES[46] | 47 | 1 (G290 SINUME RIK-mode) |
| GCODE_RESET_VALUES[47] | 48 | 3 (G462) |
| GCODE_RESET_VALUES[48] | 49 | 1 (CP) |
| GCODE_RESET_VALUES[49] | 50 | 1 (ORIEULER) |
| GCODE_RESET_VALUES[50] | 51 | 1 (ORIVECT) |
| GCODE_RESET_VALUES[51] | 52 | 1 (PAROTOF) |
| GCODE_RESET_VALUES[52] | 53 | 1 (TOROTOF) |
| GCODE_RESET_VALUES[53] | 54 | 1 (ORIROTA) |
| GCODE_RESET_VALUES[54] | 55 | 1 (RTLION) |
| GCODE_RESET_VALUES[55] | 56 | 1 (TOWSTD) |
| GCODE_RESET_VALUES[56] | 57 | 1 (FENDNORM) |
| GCODE_RESET_VALUES[57] | 58 | 1 (RELIEVEON) |
| GCODE_RESET_VALUES[58] | 59 | 1 (DYNNORM) |
| GCODE_RESET_VALUES[59] | 60 | 1 (WALCS0) |
| GCODE_RESET_VALUES[60] | 61 | 1 (ORISOF) |
| ... | | |
| ... | | |
| GCODE_RESET_VALUES[69] | 70 | 1 (not specified) |

Notes:

(exact) means that this setting is necessary in conjunction with JobShop; (variable) means that this should be seen as a suggestion and that another setting is permissible.

MD20150[15] = 3 (variable)

Group 16: Feedrate correction on internal and external curves
 Value: 3 = CFIN
 This setting provokes a constant feedrate on internal curves and acceleration on external curves

MD20150[21] = 2 (variable)

Group 22: Tool correction type
 Value: 2 = CUT2DF
 2½-D-tool correction caused by Frame
 The tool correction acts relative to the current Frame (oblique plane)

MD20150[41] = 1 (exact)

Group 42: Tool carrier
 Value: 1 = TCOABS
 Determination of the tool length components from the current tool orientation

MD20150[51] = 1 (exact)

Group 52: Tool-related Frame rotation
 Value: 1 = PAROTOF
 The tool related Frame rotation is deactivated.
 The work piece co-ordinate system is not aligned to the work piece.

MD20150[52] = 1 (variable)

Group 52: Tool-related Frame rotation
 Value: 2 = TOROTOF
 The tool related Frame rotation is de-activated.



Notes

Reset response of G groups

| | |
|----------------------------------|----------------------------|
| MD20152 \$MC_GCODE_RESET_MODE | Reset response of G groups |
| Default: 0 | Change to: |

MD20152[5] = 1 (exact)
 MD20152[7] = 1 (exact)
 MD20152[12] = 0 (exact)
 MD20152[21] = 0 (variable)

Description:

This machine datum is evaluated only if in MD20110 \$MC_RESET_MODE_MASK the Bit 0 is set. For each entry in MD20150 \$MN_GCODE_RESET_VALUES (that is for each G group) this MD is used to specify whether

- = 0: in case of a Reset/End-of-part-program the setting as per \$MC_GCODE_RESET_VALUES is used again or
- = 1: the current setting is retained after Reset/End-of-part-program

A list of the G-functional groups can be found with MD20150 MC_GCODE_RESET_VALUES.

Notes:

(exact) means that this setting is necessary in conjunction with JobShop; (variable) means that this should be seen as a suggestion and that another setting is permissible.

MD20152[5] = 1 (exact)

Group 6: Plane selection
 Value: 1
 A plane switch (e.g. G17 for facing) programmed in the part-program remains active after Reset/End-of-part-program.

MD20152[7] = 1 (exact)

Group 8: Selectable zero point offset
 Value: 1
 A zero point offset (e.g. G54) programmed in the part program remains active after Reset/End-of-part-program. This permits for example the activation of a zero point offset in the mode-of-operation JOG_T,S,M-mask Parameter zero point offset.

Description:

MD20152[12] = 0 (exact)

Group 13: Work piece dimensioning inch/metric
 Value: 0
 In the user interface it is possible in the mode-of-operation JOG Basic softkey line ">" Settings per Softkey "Switching Inch" to toggle the measuring system from metric to inch and vice versa.

MD20152[21] = 0 (variable)

Group 22: Tool correction type
 Value: 0
 After Reset/End-of-part-program the tool correction defined in MD20150[15] is activated once more. CUT2DF in this configuration example.

Activation and impact of program runtime measurement

| | |
|-----------------------------------|--|
| MD27860 \$MC_PROCESSTIMER_MODE | Activation and impact of program runtime measurement |
| Default: 0H | Change to: 73H |

- MD27860 Bit 0 = 0 → 1**
- MD27860 Bit 1 = 0 → 1**
- MD27860 Bit 4 = 0 → 1**
- MD27860 Bit 5 = 0 → 1**
- MD27860 Bit 6 = 0 → 1**

Description:

Under the function program runtime timers are provided as system variables. While the NCK-specific timers are always activated (for timings since the last control unit boot), the channel-specific timers must be started by means of this datum.

Meaning:

Bit 0 = 0
 No timing of the total runtime for all part programs



Notes

Continued MD27860

Bit 0 = 1

The timing of the total runtime for all part programs is active (\$AC_OPERATING_TIME)

Bit 1 = 0

No timing of the current program runtime

Bit 1 = 1

The measurement of the current program run-time is active (\$AC_CYCLE_TIME)

Bit 2 = 0

No timing of the tool cutting time

Bit 2 = 1

Timing of the tool cutting time is active (\$AC_CUTTING_TIME)

Bit 3

Reserved

Bits 4 only if Bit 0 and 1 = 1:

Bit 4 = 0 No timing during active test run feed motion

Bit 4 = 1 Timing also during active test run feed motion

Description:

Bit 5 = 0 No timing during program test

Bit 5 = 1 Timing also during program test

Bit 6 only if Bit 1 = 1:

Bit 6 = 0

Delete \$AC_CYCLE_TIME also after Start by ASUP and PROG_EVENTS.

Bit 6 = 1

\$AC_CYCLE_TIME will not be deleted after Start by ASUP and PROG_EVENTS.

Bit 7 only if Bit 2 = 1:

Bit 7 = 0 \$AC_CUTTING_TIME counts only with active tool.

Bit 7 = 1 \$AC_CUTTING_TIME counts independently of tool.

Bit 8 only if Bit 1 = 1:

Bit 8 = 0

\$AC_CYCLE_TIME will not be deleted in case of a jump with GOTOS to the program start.

Description:

Bit 8 = 1

\$AC_CYCLE_TIME will be deleted in case of a jump with GOTOS to the program start.

Bit 9 only if Bit 0, 1 = 1:

Bit 9 = 0

\$AC_OPERATING_TIME, \$AC_CYCLE_TIME: No timing when Override = 0.

Bit 9 = 1

\$AC_OPERATING_TIME, \$AC_CYCLE_TIME: Timing also if Override = 0.

Bit 10 to 31

Reserved

Work piece counters

A difference is made between the following work piece counters:

- Number of the command work pieces
System variable \$AC_REQUIRED_PARTS
Setting by means of Bit 0 and 1
- Total number of work pieces (actual work pieces) finished since the Start
System variable \$AC_TOTAL_PARTS
Setting by means of Bit 4, 5 and 7
- Number of all work pieces (actual work pieces) finished since the Start
System variable \$AC_ACTUAL_PARTS
Setting by means of Bit 8, 9 and 11
- Number of work pieces finished as per the own strategy
System variable \$AC_SPECIAL_PARTS
Setting by means of Bit 12, 13 and 15



Notes

Continued Work piece counters

In the user interface of the mode-of-operation AUTO the mask shown alongside can be opened by selecting Time/Counter



| Time, counter | |
|----------------------|----------|
| Program | 0:00:00h |
| Prog. remainder ca. | 0:00:00h |
| | 0% |
| Count workpieces | Yes |
| Workpieces, setpoint | 0 |
| Workpieces, actual | 0 |

- The following assignment applies:
- Parameter "Workpieces, setpoint": \$AC_REQUIRED_PARTS
 - Parameter "Workpieces, actual": \$AC_ACTUAL_PARTS

Activation of workpiece counter

| | |
|------------------------------|---------------------------------|
| MD27880 \$MC_PART_COUNTER | Activation of workpiece counter |
| Default: 0H | Change to: 901H |

MD27880 Bit 0 = 0 → 1
 MD27880 Bit 8 = 0 → 1
 MD27880 Bit 11 = 0 → 1

Bit 0 = 1: Counter \$AC_REQUIRED_PARTS is activated
Further meaning of Bit 1-3 only if Bit 0 =1 and \$AC_REQUIRED_PARTS > 0:

Further meaning of Bit 1 - 3 only if Bit 0 = 1 and \$AC_REQUIRED_PARTS > 0:

Bit 1 = 0: Alarm/VDI-output if \$AC_ACTUAL_PARTS corresponds to \$AC_REQUIRED_PARTS

Bit 1 = 1: Alarm/VDI-output if \$AC_SPECIAL_PARTS corresponds to \$AC_REQUIRED_PARTS

Bit 2: reserved

Bit 3: reserved

Bit 4 = 1: Counter \$AC_TOTAL_PARTS is active

Further meaning of Bit 5 - 7 only if Bit 4 = 1 and \$AC_TOTAL_PARTS > 0:

Bit 5 = 0: Counter \$AC_TOTAL_PARTS is increased by the value 1 after a VDI-output of M02/M30.

Bit 5 = 1: Counter \$AC_TOTAL_PARTS is increased by the value 1 after the output of the M-command from MD PART_COUNTER_MCODE[0]

Bit 6 : reserved

Bit 7 = 1: Counter \$AC_TOTAL_PARTS is increased by the value 1 after a jump back with GOTOS

Bit 8 = 1: Counter \$AC_ACTUAL_PARTS is active

Further meaning of Bit 9 - 11 only if Bit 8 = 1 and \$AC_REQUIRED_PARTS > 0:

Bit 9 = 0: Counter \$AC_ACTUAL_PARTS is increased by the value 1 after a VDI-output of M02/M30

Bit 9 = 1: Counter \$AC_ACTUAL_PARTS is increased by the value 1 after the output of the M-command from MD PART_COUNTER_MCODE[1]

Bit 10: reserved

Bit 11 = 1: Counter \$AC_ACTUAL_PARTS is increased by the value 1 after a jump back with GOTOS.

Bit 12 = 1: Counter \$AC_SPECIAL_PARTS is active

Further meaning of Bit 13-15 only if Bit 12 =1 and \$AC_REQUIRED_PARTS > 0:

Bit 13 = 0: Counter \$AC_SPECIAL_PARTS is increased by the value 1 after a VDI-output of M02/M30

Bit 13 = 1: Counter \$AC_SPECIAL_PARTS is increased by the value 1 after output of the M-command from MD PART_COUNTER_MCODE[2]

Bit 14: reserved



Notes

Continued MD27880

Bit 15 = 1: Counter \$AC_SPECIAL_PARTS is increased by the value 1 after a jump back with GOTOS.

Application example:

MD27880 PART_COUNTER = 101H
 Bit 0 = 1: Counter \$AC_REQUIRED_PARTS "Work pieces Command" activate
 Bit 8 = 1: Counter \$AC_ACTUAL_PARTS "Work pieces Actual" activate

MD 27882[1] PART_COUNTER_MCODE = 32

Part program:

In such a JobShop-Program the program repeat can be switched ON in the automatically generated End-of-program block by means of the parameter "Repetition". In this case the command GOTOS will be generated.

In a G code part program the program repetition can be done by

- the command GOTOS or#
-
GOTOS ;Repeat
M30
- a self-defined M command
...
M33 ; Repeat
M30

The number of work pieces is to be set in the mode-of-operation AUTO in the mask "Time/Counter" by the parameter "Workpieces, setpoint".

Relevant PLC interface signals:

Activating the part program repetition is done by setting the PLC interface signal "Chan1".A_ProgJump//DB21.DBX384.0 to 1.

When the actual number of workpieces matches the number of setpoint the PLC interface signal "Chan1".E_WS_Step//DB21.DBX317.1 is set to 1.

Memory space for REORG (DRAM)

| | |
|---|-------------------------------|
| MD28000 \$MC_MM_REORG_LOG_ FILE_MEM | Memory space for REORG (DRAM) |
| Default: 50 | Change to: 75 |

Number of blocks for local user variables in REORG (DRAM)

| | |
|--|---|
| MD28010 \$MC_MM_NUM_REORG_ LUD_MODULES | Number of blocks for local user variables in REORG (DRAM) |
| Default: 8 | Change to: 20 |

Projecting of channel-specific system frames

| | |
|--|----------------------|
| MD28082 \$MC_MM_SYSTEM_FRAME_ MASK | System frames (SRAM) |
| Default: 21H | Change to: |

**Bit 0 = 1 System frame for Actual value set and scratching
 Bit 5 = 1 System frame for cycles**

Description:

Bit-mask for the projecting of channel-specific system frames, which are evaluated in the channel.

- Bit 0: System frame for actual value set and scratching
- Bit 1: System frame for external zero point offset
- Bit 2: System frame for TCARR and PAROT
- Bit 3: System frame for TOROT and TOFRAME
- Bit 4: System frame for work piece reference points
- Bit 5: System frame for cycles
- Bit 6: System frame for transformations
- Bit 7: System frame \$P_ISO1FR for ISO G51.1 mirror
- Bit 8: System frame \$P_ISO2FR for ISO G68 2DROT
- Bit 9: System frame \$P_ISO3FR for ISO G68 3DROT
- Bit 10: System frame \$P_ISO4FR for ISO G51 Scaling
- Bit 11: System frame \$P_RELFR for rel. co-ordinate systems

Note:

The system frames for actual value set and scratching (basic reference=) and for cycles are required for Job-Shop installations.



Notes

JOG-TSM

In the operation mode JOG the input masks for "T,S,M", "Position" and "Face milling" are available. These permit simple functions to be carried out such

- T,S,M: Tool changes, spindle functions, ZPO-selections
- Position: axes and spindles positioning
- Face milling: roughing of a corner with chamfers and/or radii.

After the data have been entered and NC-Start initiated the file MA_JOG_STEP1.MPF will be generated in the directory "Workpieces - TEMP " in the program-manager and executed.

To ensure that such functions as e. g. tool selection and spindle Start will remain activated also after reset and end-of program, respective machine data are required, which will be described below.

The settings will be described with the T,S,M-Mask; the input masks Position and Roughing do not require special settings.

Bit 6 = 1:

The current setting for the active tool length correction remains active also after Reset/end-of-part program. If the tool or magazine management is active, that tool is selected which happens to be in the master spindle (generally referred to as master-tool holder). If the tool in the master spindle is locked, the "locked" status will be ignored.

It must be borne in mind that after end-of-program, program abort either the last programmed value for the master spindle respectively the master tool holder or else the value specified by \$MC_SPIND_DEF_MASTER_SPIND respectively \$MC_TOOL_MANAGEMENT_TOOLHOLDER for the master spindle respectively the master-tool holder will be used.

Tool change

Definition of basic control settings after reset/PP end

| | |
|---------------------------------|---|
| MD20110 \$MC_RESET_MODE_MASK | Definition of basic control settings after reset/PP end |
| Default: 1H | Change to: 4041H |

MD20110 = 1H → 4041H

Bit 6 = 0 → 1

Description:

Bit 6: Reset behaviour "active tool length correction"

Activation of tool management functions

| | |
|--------------------------------------|---|
| MD20310 \$MC_TOOL_MANAGEMENT_MASK | Activation of tool management functions |
| Default: 0H | Change to: 80400BH |

Bit 0 - 3 must be set as in MD18080 \$MN_MM_TOOL_MANAGEMENT_MASK

- Bit 0 = 0 → 1 Magazine management active
- Bit 1 = 0 → 1 Monitoring functions active
- Bit 3 = 0 → 1 Adjacent location treatment
- Bit 14 = 0 → 1 autom. tool change during Reset and Start**
- Bit 23 = 0 → 1 On offset selection no synchronization with HL

Description:

Bit 14 = 1: Reset-Mode
Tool and correction selection as per the settings of MD20110 \$MC_RESET_MODE_MASK and MD20112 \$MC_START_MODE_MASK.

Bit 14 = 0: No Reset mode



Notes

Spindle

These settings are required to enable spindles to be started from the T,S,M mask.

M function for spindle active after reset

| | |
|------------------------------|---|
| MD10714 \$MN_M_NO_FCT_EOP | M function for spindle active after reset |
| Default: -1 | Change to: 32 |

MD10714 = -1 → 32 (Suggestion M32)

Description:

With Start in the manual mode-of-operation (T,S,M-mask, position) the part-program MA_JOG_STEP1 will be generated and executed. This part-program will be finished with the M-function in MD10714. The setting of MD35040 = 2 ensures that the spindle remains active also after the end-of-program.

Limitations see MD10715 \$MN_M_NO_FCT_CYCLE

Own spindle RESET

| | |
|--|-------------------|
| MD35040 \$MA_SPIND_ACTIVE_AFTER_RESET | Own spindle RESET |
| Default: 0 | Change to: 2 |

MD35040 = 0 → 2

Description:

MD35040 \$MA_SPIND_ACTIVE_AFTER_RESET defines the response of the spindle after channel reset NC/PLC interface signal DB21-30 DBX7.7 (Reset) and program end (M2, M30).

This MD is only active in the spindle mode open-loop control mode. In the positioning or oscillation mode, the spindle is always stopped.

Settings for the control unit:

AX4:SP1
MD35040 =0 → 2 Own spindle-RESET

MD35040 \$MA_SPIND_ACTIVE_AFTER_RESET = 0:

- Spindle stops (with M2/M30 and channel and mode group reset)
- Program is aborted

MD35040 \$MA_SPIND_ACTIVE_AFTER_RESET= 1:

- Spindle does not stop
- Program is aborted

MD35040 \$MA_SPIND_ACTIVE_AFTER_RESET= 2:

- Spindle does not stop at the M function configured via MD10714 \$MN_M_NO_FCT_EOP (e.g. M32).
- However, the spindle stops at channel or mode group reset.

The NC/PLC interface signal DB31, ... DBX2.2 (Delete distance-to go/ Spindle reset) is always effective, independent of MD35040 \$MA_SPIND_ACTIVE_AFTER_RESET.

Not relevant to:

- Spindle modes other than open-loop control mode.

Corresponds to:


NC/PLC interface signal DB21-30 DBX7.7 (Reset)

NC/PLC interface signal DB31, ... DBX2.2 (Delete distance-to go/spindle reset)

Start main spindle via the T,S,M-mask


T,S,M-mask with inputs for spindle speed and direction of rotation of the main spindle S1

Enter speed and direction of rotation



and actuate NC-Start

MA_JOG_STEP1 is generated



Notes

Continued Start main spindle via the T,S,M-mask

Description:

- M3 G972 S1=1000
Starting of the spindle


Note:

In case of a ShopMill installation there will be no CUST_TECHCYC call-ups for the spindle control from the T,S,M-mask and during program execution.

Note on spindle direction of rotation:

The assignment of the direction arrow for the spindle M-function M3/M4 is effected via the MD52207 \$MCS_AXIS_USAGE_ATTRIB.

Monitoring the tool change



Shown in the T,F,S-field is the tool currently loaded in the spindle.

Select tool



Use the cursor keys to select the required tool and thereafter transfer it by means of the Soft-Key "In manual".

| Loc. | Type | Tool name | ST | D | Length | ø | N | ↓ | ↺ | ↻ | M | 1 |
|------|------|----------------|----|---|--------|--------|-------|---|---|---|---|---|
| | | WIST_DRILL_8 | 1 | 1 | 0.000 | 8.000 | 118.0 | ↺ | | | | |
| 1 | | END_MILL_10 | 1 | 1 | 10.000 | 10.000 | | 4 | ↺ | | | |
| 2 | | END_MILL_20 | 1 | 1 | 0.000 | 20.000 | | 4 | ↺ | | | |
| 3 | | | | | | | | | | | | |
| 4 | | WIST_DRILL_12 | 1 | 1 | 0.000 | 12.000 | 118.0 | ↺ | | | | |
| 5 | | TAP_M10 | 1 | 1 | 0.000 | 10.000 | 3.000 | ↺ | | | | |
| 6 | | FACING TOOL_30 | 1 | 1 | 0.000 | 8.000 | | 0 | ↺ | | | |
| 7 | | | | | | | | | | | | |
| 8 | | | | | | | | | | | | |
| 9 | | | | | | | | | | | | |
| 10 | | | | | | | | | | | | |
| 11 | | | | | | | | | | | | |
| 12 | | | | | | | | | | | | |
| 13 | | | | | | | | | | | | |
| 14 | | | | | | | | | | | | |
| 15 | | | | | | | | | | | | |
| 16 | | | | | | | | | | | | |
| 17 | | | | | | | | | | | | |




Notes

Loading the new tool

In manual



The selected tool "Finisher" is now displayed in the T,S,M mask.



The tool will be loaded into the T,F,S mask with Cycle Start. The PLC-tool change functions provided by the machine manufacturer are executed in the background for this process.

Gear step

Parameterize gear stage change

| | |
|---|--------------------------------|
| MD35010 \$MA_GEAR_STEP_CHANGE_ENABLE | Parameterize gear stage change |
| Default: 0H | Change to: 1H |

Number of gear stages

| | |
|--------------------------------|-----------------------|
| MD35090 \$MA_NUM_GEAR_STEPS | Number of gear stages |
| Default: 5 | Change to: |

Description:

Number of prepared gear stages.
The first gear stage is always activated.

Note:

The selection field Gear stage appears only if in MD35010 for the spindle Bit 0 = 1 is set.



With NC-Start the program MA_JOG_STEP1 will be generated - in this example for the selection of the gear stage 2 = M42.

```
NC/WKS/TEMP/MA_JOG_STEP1
PROC MA_JOG_STEP1 SBL0F
CYCLE210(0)
M42
M32
```



Notes

Inch/Metric-switching



Below once again a summation of the machine data settings required for Inch/Metric-switching.

Enable basic system conversion

| | |
|--|--------------------------------|
| MD10260 \$MN_CONVERT_SCALING_SYSTEM | Enable basic system conversion |
| Default: 0 | Change to: 1 |

Description:

Switching the measuring systems with HMI-Softkey
 0. Hide Softkey inch/metric switching
 1. Display Softkey inch/metric switching
 Selection of Inch/Metric-switching:



Note:

MD 20152[12] = 0 must be set for the position readouts to be converted.

Block search

Parameterization for block search

| | |
|---------------------------------|-----------------------------------|
| MD11450 \$MN_SEARCH_RUN_MODE | Parameterization for block search |
| Default: 0H | Change to: 7H |

Bit 0 = 0 → 1 Put out alarm 10208 to PROG_EVENT

Bit 1 = 0 → 1 automatic ASUP-Start (PROG_EVENT)

Bit 2 = 0 → 1 No collection of auxiliary functions

Function mask Cross-technology

| | |
|-------------------------------------|--------------------------------|
| MD52212 \$MCS_FUNCTION_MASK_TECH | Function mask Cross-technology |
| Default: 0H | Change to: 8H |

Bit 3 = 0 → 1

Description:

- Bit 0: Enabled Swivel
- Bit 1: No optimized travel along software limit switches
- Bit 2: Approach logic for step drill (ShopTurn)
- Bit 3: Call block search-cycle for ShopMill/ShopTurn**
- Bit 4: Approach logic through cycle (ShopTurn)
- Bit 5: Call block search cycle for SERUPRO
- Bit 6: Work offset value ZV cannot be entered (ShopTurn)

Note:

The setting of Bit 3=1 ensures that the tool programmed after the block search is duly changed and that the spindle rotates in the tool-assigned direction at the speed programmed in the destination block. For installations without ShopMill this Bit needs not to be set, however, the machine manufacturer must ensure that the tool and spindle functions are gathered and put out during the block search.



Notes

Tool change commands to PLC after search run

| | |
|-------------------------------------|--|
| MD20128 \$MC_COLLECT_TOOL_CHANGE | Tool change commands to PLC after search run |
| Default: 1 | Change to: 0 when ShopMill/ShopTurn |

MD20128 = 1 → 0 No gathering of tools during the block search

Description:

This MD is of any meaning only with activated magazine management (MD18080 \$MN_MM_TOOL_MANAGEMENT_MASK, MD20310 \$MC_TOOL_MANAGEMENT_MASK). It specifies whether after block search with evaluation tool changing commands, tool preparation commands (generally tool changing commands) are put out to the PLC or not put out to the PLC.

1: Tool changing commands and tool preparation commands are gathered and passed on to the PLC with program Start when the search run has attained the destination block.

0: all tool and/or magazine specific commands that were gathered during the block search will not be put out to the PLC with the next program Start! That means that also programmed POSM, TCI, TCA will not be passed on to the PLC.

Note 1:

Without an active magazine management the tool change-M-code will not be gathered, if it is not assigned to an auxiliary function group. With an active magazine management this corresponds to an MD-value = 0.

Note 2:

The value = 0 is sensible for instance if after reaching the search destination the gathered tool change commands are transferred to the PLC in an ASUP-program with the aid of the commands GETSELT, GETEXET.

Simulation

Adjustment of SZS co-ordinate system (settable zero system)

| | |
|-------------------------------|--------------------------------------|
| MD24030 \$MC_FRAME_ACS_SET | Adjustment of SZS co-ordinate system |
| Default: 0 | Change to: 1 |

MD24030 = 0 → 1

Description:

0: SZS results from the WCS transformed with \$P_CYCFRAME and \$P_PFRAME.

1: SZS results from the WCS transformed with \$P_CYCFRAME.

The position readouts show the SZS-co-ordinate system if "WCS" is selected.

Axis position at start of simulation

| | |
|-------------------------------------|--------------------------------------|
| MD53230 \$MAS_SIM_START_POSITION | Axis position at start of simulation |
| Default: 0 | Change to: 500, 500, 200 mm |

AX1: X1
MD53230 = 0 → e.g. 500 mm

AX2: Y1
MD53230 = 0 → e.g. 500 mm


AX3: Z1
MD53230 = 0 → e.g. 200 mm

Description:

Axis position at the Start of the simulation.

Note:

For the further axes and spindles this MD should be left on 0.



Depiction of the co-ordinate systems and the Frame chain 

| |
|-------|
| Notes |
|-------|

Notes

Menu and Technology settings

Machine → JOG



Notes

Machine → JOG → WCS

SIEMENS

Workpiece Position [mm]

X 0.000

Y 0.000

Z 0.000

A 0.000°

C 0.000°

T,F,S TISCH

T FACEMILL60 ∅60.000 L100.000

D1

F 0.000 mm/min 100%

S1 0

Master 0 50% 100%

MD20098[X] Bit 16 = WCS actual value window

Buttons: T,S,M, Set U0, Meas. workp., Meas. tool, Position, Face mill.

| Softkey selection | Description |
|---------------------|---|
| G functions | |
| Auxiliary functions | |
| Act. values Machine | Switchover Softkey from MCS to WCS via PLC (DB19) |

Machine → JOG → MCS

SIEMENS

Machine Position [mm]

X1 0.000

Y1 0.000

Z1 0.000

A1 0.000°

C1 0.000°

T,F,S TISCH

T FACEMILL60 ∅60.000 L100.000

D1

F 0.000 mm/min 100%

S1 0

Master 0 50% 100%

MD51023 ACT_VALUE_SPIND = 1
Spindles are displayed only if in axis mode, SP1 not displayed (Default setting)

MD51023 ACT_VALUE_SPIND = 0
Spindles are always displayed (Scroll bar on the right, down)

alternative

Buttons: T,S,M, Set U0, Meas. workp., Meas. tool, Position, Face mill.

| Softkey selection | Description |
|---------------------|---|
| G functions | |
| Auxiliary functions | |
| Act. values Machine | Switchover Softkey from MCS to WCS via PLC (DB19) |



Notes

Machine → JOG → T,S,M

MD20110 RESET_MODE_MASK
Bit 6 = 1 Tool length compensation is retained even after RESET MD20130 = 1 Tool and tool edge number retain

MD20310 TOOL_MANAGEMENT_MASK
Bit 16 = 0 Tool name

MD20310 TOOL_MANAGEMENT_MASK
Tool management function mask
Bit 14 = 1 Automatic Tool change during Reset and Start

| Workpiece | Position [mm] | T,F,S |
|-----------|---------------|--------------|
| X | 0.000 | T FACEMILL60 |
| Y | 0.000 | D1 |
| Z | 0.000 | F 0.000 |
| A | 0.000° | S1 0 |
| C | 0.000° | Master 0 |

T.S.M
T CUTTER_63 D 1
Spindle 2000.000 rpm
Spindle M function 2
Other M function
Work offset Basic ref.
Machining plane G17 (XY)

Machine → JOG → T,S,M

MD35040 SPIND_ACTIV_AFTER_RESET
= 2 Own spindle reset

MD35000 AX4:SP1 = 1
The spindle must be configured

MD35010 GEAR_STEP_CHANGE_ENABLE of AX4:SP1 Bit 1 = 1
and
MD35090 NUM_GEAR_STEPS of SP1 Number of gear steps = 5

| Workpiece | Position [mm] | T,F,S |
|-----------|---------------|----------|
| X | 0.000 | TISCH |
| Y | 0.000 | D1 |
| Z | 0.000 | F 0.000 |
| A | 0.000° | S1 0 |
| C | 0.000° | Master 0 |

T.S.M
T D 1
Spindle rpm
Spindle M function
Other M function
Gear stage Auto
I
II
III
IV
V



Notes

Machine → JOG → T,S,M

SIEMENS

01/10/94 11:31 PM

Reset

| Workpiece | Position [mm] | T,F,S | TISCH |
|-----------|---------------|--------------|-------------------|
| X | 0.000 | T FACEMILL60 | ∅60.000 |
| Y | 0.000 | D1 | L0.000 |
| Z | 0.000 | F 0.000 | 0.000 mm/min 100% |
| A | 0.000° | S1 0 | 50% |
| C | 0.000° | Master 0 | 50% |

MD20152[7] G_CODE_RESET_MODE = 1 Work
Work offset is retained even after Reset

T,S,M

T D 1

Spindle G54 rpm

Spindle M function G55

Other M function G56

Work offset G57

Machining plane

G17 (XY)
G18 (ZX)
G19 (YZ)

MD20152[5] G_CODE_RESET_MODE = 1
Switch over machining plane

MD52005 DISP_PLANE_MILL = 0
Plane selection on the operator panel

Back

T,S,M Set UO Meas. workp. Meas. tool Position Face mill.

Machine → JOG → Set WO

SIEMENS

01/10/94 11:34 PM

Reset

| Workpiece | Position [mm] | T,F,S | TISCH |
|-----------|---------------|--------------|-------------------|
| X | 0.000 | T FACEMILL60 | ∅60.000 |
| Y | 0.000 | D1 | L0.000 |
| Z | 0.000 | F 0.000 | 0.000 mm/min 100% |
| A | 0.000° | S1 0 | 50% |
| C | 0.000° | Master 0 | 50% |

G54

X=0
Y=0
Z=0
X=Y=Z=0

Delete active UO

Back


The softkey is highlighted if no G500 is active and MCS is not selected

T,S,M Set UO Meas. workp. Meas. tool Position Face mill.




Notes

Machine → JOG → Measure workpiece



| Softkey selection | Description |
|----------------------|---|
| SD54780 Bit 2 = 1 | Bit 2 = 1 Activate calibration for electronic workpiece probe |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Machine → JOG → Measure workpiece



Notes

Machine → JOG → Measure workpiece

SIEMENS

01/11/94
12:44 AM

Reset

| Workpiece | Position [mm] | T,F,S | TISCH |
|-----------|---------------|--------------|-------------|
| X | 0.000 | T FACEMILL60 | ∅60.000 |
| Y | 0.000 | D1 | L0.000 |
| Z | 0.000 | F 0.000 | mm/min 100% |
| A | | S1 0 | |
| C | | Master 0 | 50% |

SD54780 Bit 3 = 1
Select probe calibration data field

Calibrate: probe

Probe length L 0.000
Related to probe ball size
Trigger point -Z

1
20 1
2
3
4
5
6
7
8
9
10

Back

Machine → JOG → Measure workpiece

SIEMENS

09/23/11
4:08 PM

Reset

| Workpiece | Position [mm] | T,F,S | |
|-----------|---------------|-------------|-------------|
| X | 0.000 | T CUTTER_10 | ∅10.000 |
| Y | 0.000 | D1 | L100.000 |
| Z | 0.000 | F 0.000 | mm/min 100% |
| A | | S1 0 | 100% |
| C | | Master 0 | |

MD52207[X] AXIS_USAGE_ATTRIB, Axis attributes
Bit 6 = 1: Show rotary axis as offset target for measuring

Measure: align edge

Values UO 20
Measured values 0.000

Align edge
Work offset G54
Meas. axis + Selection
Angle offs. Coord. rotat.
Spec. angle Coord. rotat.
Rot. axis C


Example:
MD52207[5] AXIS_USAGE_ATTRIB = 44H
Bit 6 = 1: Show rotary axis as correction destination for measuring in addition to coordinate rotation

Back




Notes

Machine → JOG → Measure tool



| Softkey selection | Description |
|-------------------|---|
| | |
| | |
| SD54782 Bit 2 = 1 | Bit 2 = 1 Enable automatic tool measurement |
| SD54782 Bit 2 = 1 | Bit 2 = 1 Enable automatic tool measurement |
| | |
| SD54782 Bit 2 = 1 | Bit 2 = 1 Enable automatic tool measurement |
| | |
| | |

Machine → JOG → Measure tool



Notes

Machine → JOG → Position

SIEMENS

Workpiece Position [mm]

| | |
|---|--------|
| X | 0.000 |
| Y | 0.000 |
| Z | 0.000 |
| A | 0.000° |
| C | 0.000° |

T,F,S TISCH

T FACEMILL60 ∅60.000
D1 L8.000

F 0.000 mm/min 100%

S1 0

Master 0 50%

Target position

| | | |
|-----|-------------|--------|
| F | *Rapid tr.* | mm/min |
| X | | abs |
| Y | | abs |
| Z | | abs |
| SP1 | | abs |
| A | | abs |
| C | | abs |

not displayed

Buttons: T,S,M, Set W0, Meas. workp., Meas. tool, Position, Face mill.

Machine → JOG → Face milling

SIEMENS

SD55200 MAX_INP_FEED_PER_REV, Upper limit feedrate/rev
SD55201 MAX_INP_FEED_PER_TIME, Upper limit feedrate/min
SD55202 MAX_INP_FEED_PER_TOOTH, Upper limit feedrate/tooth

Face milling

T D1

F 50.000 mm/min

S 2000.000 rpm

Machining Direction

| | |
|-----|------------|
| X0 | 15.000 |
| Y0 | 20.000 |
| Z0 | 0.200 |
| X1 | 10.000 inc |
| Y1 | 15.000 inc |
| Z1 | 5.000 inc |
| DXY | 0.600 mm |
| DZ | 0.500 |
| UZ | 0.100 |

SD43220 SPIND_MAX_VELO_G26, Programmable upper spindle limitation G26
SD43230 SPIND_MAX_VELO_LIMS, Spindle speed limitation with G96

Buttons: T,S,M, Set W0, Meas. workp., Meas. tool, Position, Face mill.



Notes

Machine → JOG → Settings

The screenshot shows the 'Settings for manual mode' screen. At the top, there's a 'Reset' button and the 'SIEMENS' logo. Below that, a table shows workpiece positions (X, Y, Z, A, C) all at 0.000 mm. The tool is 'T FACEMILL60' with diameter 60.000 mm and length 10.000 mm. The feed rate 'F' is 0.000 mm/min at 100% speed. The spindle speed 'S1' is 0 rpm. The 'Settings for manual mode' section includes: 'Type of feed' (G94), 'Set-up feedrate G94' (G94), 'Set-up feedrate G95' (0.200 mm/rev), 'Variable increment' (0), and 'Spindle speed' (100 rpm). A red arrow points from the 'Settings' softkey to the 'MD10260 CONVERT_SCALING = 1' parameter.

| Softkey selection | Description |
|-------------------|------------------------------------|
| | |
| | |
| | |
| | |
| MD10260 = 1 | =1: Enable basic system conversion |
| | |
| | |
| | |

The screenshot shows the 'Settings' softkey menu. The 'Settings' softkey is highlighted. A line connects it to the 'MD51067=1' parameter in the table below.

| Softkey selection | Description |
|-------------------|---|
| | |
| | |
| | |
| MD51067=1 | =1: Show handwheel window (Handwheel must be configured in MD11350) |
| | |
| | |
| | |
| | |



Notes

Parameter → Tool list

MD52270 TM_FUNCTION_MASK
Bit 0 = 1 Create tool on magazine location not allowed
Bit 7 = 1 Create tool using the tool number

SD54215 TM_FUNCTION_MASK_SET
Bit 2 = 1 Create tool without name suggestion
Bit 3 = 1 Input disable for tool name and tool type in loaded tools
Bit 4 = 1 Input disable for loaded tools, if the channel is not in Reset
Bit 11 = 1 Creating tool in gripper disabled

| Softkey selection | Description |
|----------------------|----------------------------------|
| | |
| | |
| | |
| MD19320 Bit 4 = 1 | Bit 4 = 1 Enable Tool Management |
| | |
| | |
| | |



Notes

Parameter → Tool list

| Loc. | MT LO. | Type | Tool name | ST | D | Length | ∅ | N | M |
|------|--------|------|-------------|----|---|---------|--------|------|---|
| 1 | | | FRAESER10 | 1 | 1 | 150.000 | 10.000 | 4 | 1 |
| 2 | | | | | | | | 4 | 2 |
| 3 | | | | | | | | 2 | 2 |
| 4 | | | | | | | | 2 | 2 |
| 5 | | | BALL_D12_F | 1 | 1 | 150.000 | 12.000 | 2 | 2 |
| 6 | | | BULL_D25_R5 | 1 | 1 | 11.000 | 0.000 | 2 | 2 |
| 7 | | | 3D_TASTER | 1 | 1 | 11.000 | 0.000 | 2 | 2 |
| 8 | | | BALL_D8 | 1 | 1 | 11.000 | 0.000 | 2 | 2 |
| 9 | | | BALL_D4 | 1 | 1 | 11.000 | 0.000 | 2 | 2 |
| 10 | | | BALL_D4 | 1 | 1 | 11.000 | 0.000 | 2 | 2 |
| 11 | | | BULL_D32_R5 | 1 | 1 | 150.000 | 32.000 | 4 | 2 |
| 12 | | | BALL_D10_R | 1 | 1 | 472.166 | 10.000 | 2 | 2 |
| 13 | | | 10 | 1 | 1 | 150.000 | 12.000 | 2 | 2 |
| 14 | | | | | | | | 2 | 2 |
| 15 | | | FRAESER8 | 1 | 1 | 11.000 | 0.000 | 4 | 2 |
| 16 | | | ZENT8 | 1 | 1 | 11.000 | 0.000 | 2 | 2 |
| 17 | | | BOHRER_M6 | 1 | 1 | 11.000 | 0.000 | 18.0 | 2 |

Parameter → Tool wear

| Loc. | MT LO. | Type | Tool name | ST | D | Length | Δ ∅ | T C | Quantity | Set val | Prewar limit |
|------|--------|------|-------------|----|---|--------|-------|-----|----------|---------|--------------|
| 1 | | | FRAESER10 | 1 | 1 | 11.000 | 0.000 | T | 0.0 | 0.0 | 0.0 |
| 4 | | | BALL_D6_F | 1 | 1 | 11.000 | 0.000 | | | | |
| 5 | | | BALL_D12_F | 1 | 1 | 11.000 | 0.000 | | | | |
| 6 | | | BULL_D25_R5 | 1 | 1 | 11.000 | 0.000 | C | 0 | 0 | 0 |
| 7 | | | 3D_TASTER | 1 | 1 | 11.000 | 0.000 | | | | |
| 8 | | | BALL_D8_R | 1 | 1 | 11.000 | 0.000 | | | | |
| 9 | | | BALL_D4_R | 1 | 1 | 11.000 | 0.000 | | | | |
| 10 | | | BALL_D4_F | 1 | 1 | 11.000 | 0.000 | | | | |
| 11 | | | | | | | 0.000 | | | | |
| 12 | | | | | | | 0.000 | T | 0.0 | 0.0 | 0.0 |
| 13 | | | 10 | 1 | 1 | 11.000 | 0.000 | | | | |
| 14 | | | | | | | 0.000 | | | | |
| 15 | | | FRAESER8 | 1 | 1 | 11.000 | 0.000 | | | | |
| 16 | | | | | | | 0.000 | | | | |
| 17 | | | | | | | 0.000 | | | | |

| Softkey Sichtbar | Description |
|--------------------|-----------------------------------|
| | |
| | |
| | |
| | |
| | |
| MD52270 Bit 12 = 0 | Bit 12 = 0 Enable Reactivate tool |
| | |
| | |



Notes

Parameter → Magazine

| Loc. | MT LO. | Type | Tool name | ST | D | D | Z | L |
|------|--------|------|-------------|----|---|---|---|---|
| 1 | | | FRAESER10 | 1 | 1 | | | |
| 2 | | | BULL_D35_R6 | 1 | 1 | | | |
| 3 | | | BALL_D12_R | 1 | 1 | | | |
| 4 | | | BALL_D6_R | 1 | 1 | | | |
| 5 | | | BALL_D6_F | 1 | 1 | | | |
| 6 | | | BULL_D25_R5 | 1 | 1 | | | |
| 7 | | | 3D_TASTER | 1 | 1 | | | |
| 8 | | | BALL_D8_R | 1 | 1 | | | |
| 9 | | | BALL_D4_R | 1 | 1 | | | |
| 10 | | | BALL_D4_F | 1 | 1 | | | |
| 11 | | | BULL_D32_R5 | 1 | 1 | | | |
| 12 | | | BALL_D10_R | 1 | 1 | | | |
| 13 | | | 10 | 1 | 1 | | | |
| 14 | | | | | | | | |
| 15 | | | FRAESER8 | 1 | 1 | | | |
| 16 | | | ZENT8 | 1 | 1 | | | |
| 17 | | | BOHRER_M6 | 1 | 1 | | | |
| 18 | | | KALI_LASER | 1 | 1 | | | |

MD52270 TM_FUNCTION_MASK
 Bit 8 = 1 Fade out Relocate tool
 Bit 9 = 1 Fade out Position magazine

| Softkey selection | Description |
|----------------------|------------------------------------|
| | |
| | |
| | |
| | |
| MD52270 Bit 8 = 0 | Bit 8 = 0 Enable Relocate tool |
| MD52270 Bit 9 = 0 | Bit 9 = 0 Enable Position magazine |
| | |
| | |

Parameter → Load tool

MD52270 TM_FUNCTION_MASK
 Bit 1 = 1 Load/unload disable, if machine is not in reset
 Bit 2 = 1 Load/unload disable on Emergency stop
 Bit 3 = 1 Load/unload tool to/from spindle is disabled
 Bit 4 = 1 Loading is executed directly in the spindle

MD52274 TM_TOOL_LOAD_STATION
 Default setting = 0 All configured stations are taken into account

Select loading point

Loading point 1; Loading point 2

Loading point 1



Notes

Parameter → Load tool


| Softkey selection | Description |
|--------------------|--|
| | |
| | |
| | |
| | |
| Spindle | |
| Multitool | |
| | |
| Cancel | |
| OK | |
| MD18080 Bit 10 = 1 | Bit 10 = 1 The multitool function is available |

Parameter → Setting data



Notes

Machine → MDA



Notes

Machine → AUTO → Time / Counter

| Softkey selection | Description |
|----------------------------|---|
| | |
| | |
| MD28400 = 1 | =1: Activate basic blocks with absolute values |
| MD27860 Bit 0 or Bit 8 = 1 | =1: Softkey Time/Counter =0: Softkey Times (Default setting) |
| | |
| | |
| | |
| | |
| | |
| | |

| Softkey selection | Description |
|-------------------|--|
| | |
| Option P22 | Simultan. recording (real-time simulation) |
| | |
| | |
| | |
| | |
| | |
| | |



Notes

Machine → AUTO → Overstore

Machine → AUTO → Program control



Notes

Machine → AUTO → Block search (ShopMill)

| Softkey selection | Description |
|-------------------|--|
| Start search | |
| Blk sear. mode | MD51024 Bit 0 und Bit 1 = 1 Bit mask for available search modes in ShopMill program |
| Higher level | |
| Lower level | |
| Search for text | |
| Interrupt point | |
| Search pointer | |
| Back | |

Machine → AUTO → Block search (G code program)

| Softkey selection | Description |
|-------------------|--|
| Start search | |
| Blk sear. mode | MD51028 Bit 0 und Bit 1 = 1 Bit mask for available search modes in G code program |
| Higher level | |
| Lower level | |
| Search for text | |
| Interrupt point | |
| Search pointer | |
| Back | |



Notes

Program → Edit

01/03/94
1:53 AM

NC/WKS/SHOPMILL/DEMO_PROGRAM

| | | | |
|---|-----|--------------------|--|
| P | N5 | Program header | Work offset G54 |
| | N15 | Face milling | T=MESSERKOPF_63 F0.4/t V=200m X0=-80 Y0=80 |
| | N20 | Contour | TASCHE |
| | N25 | Contour | INSEL |
| | N30 | Mill pocket | T=FRAESER_25 F0.3/t V=200m Z0=0 Z1=10inc |
| | N35 | Pocket resid.mat. | T=FRAESER_10 F0.25/t V=200m Z0=0 Z1=10inc |
| | N40 | Mill pocket | T=FRAESER_10 F0.2/t V=250m Z0=0 Z1=10inc |
| | N45 | Mill pocket | T=FRAESER_10 F0.2/t V=250m Z0=0 Z1=10inc |
| | N50 | Centering | T=ZENTRIERER_20 F0.1/rev S=3000rev ø13 |
| | N55 | Deep hole drill. | T=BOHRER_10 F0.1/rev V=50m Z1=40inc |
| | N60 | Tapping | T=GEWINDE_M12 P1.75mm/rev V=40m Z1=35inc |
| | N65 | ØØ1: Posit. circle | Z0=0 X0=0 Y0=0 R=70 N=8 |
| | N70 | ØØ2: Positions | Z0=0 X0=0 Y0=0 |
| | END | End of program | |

MD52200 TECHNOLOGY = 2 Milling

Softkey menu: Select tool, Build group, Search, Mark, Copy, Paste, Cut

Bottom bar: Edit, Drilling, Milling, Cont. mill., Various, Simulation, Execute

| Softkey selection | Description |
|-------------------|------------------------|
| | |
| | |
| MD52200 = 2 | =2: Technology Milling |
| | |
| MD52200 = 2 | =2: Technology Milling |
| MD52200 = 2 | =2: Technology Milling |
| MD52200 = 2 | =2: Technology Milling |
| | |



Notes

Program manager → New

| Softkey selection | Description |
|-------------------|-------------------|
| | |
| | |
| Option P17 | ShopMill/ShopTurn |
| | |
| | |
| | |
| | |
| | |

Program → Edit



Notes

Program → Edit → Program header

NC/WKS/SHOPMILL/SHOPMILL_TEST

Program header

Unit of measu

Work offset

Blank

XA

ZA

ZI

PL

Retraction plane

RP

Safety distance

SC

Machining sense

Retract position pattern

MD52210 FUNCTION_MASK_DISP
Bit 0 = 0 Unhides input filed for mm/
inch

MD52005 DISP_PLANE_MILL
= 0 plane selection on the operator panel

Work offset

Graphic view

Cancel

Accept

Edit Drilling Milling Cont. mill. Various Simulation Execute

Program → Edit → Program header

NC/WKS/SHOPMILL/SHOPMILL_TEST

Program header

Unit of measu

Work offset

Blank

XA

ZA

ZI

PL

Retraction plane

RP

Safety distance

SC

Machining sense

Retract position pattern

SC = Safety distance

SD55214 FUNCTION_MASK_MILL_SET
Bit 2 = 1 Depth calculation in milling cycles w/o SC
Default setting = 1

SD55214 FUNCTION_MASK_MILL_SET
Bit 0 = 1 Milling cycles with synchronous operation
Default setting = 1

Work offset

Graphic view

Cancel

Accept

Edit Drilling Milling Cont. mill. Various Simulation Execute



Notes

Program → Drilling

12/10/14 18:12 PM

NC/WKS/SHOPMILL/SHOPMILL TEST

MD52216 FUNCTION_MASK_DRILL
 Bit 0 CYCLE 84 (w/o compensat. chuck)
 Bit 1 CYCLE 840 (with compensat. chuck)
 CYCLE 840 for ShopMill only

Tapping

T D 1

Table None

P 2.000 mm/rev
 S 2000.000 rpm
 SR 5.000 rpm

Z1
 W/o compensat. chuck
 With compensat. chuck
 W/o compensat. chuck

Technology Yes
 Exact stop
 Fdw. control
 Acceleration
 Spindle Speed-contr

MD52216 FUNCTION_MASK_DRILL
 Bit 0 = 1 Unhide input fields Technology

Accept

Program → Drilling

01/03/14 1:46 AM

NC/WKS/SHOPMILL/DEMO_PROGRAM

SD55216 FUNCTION_MASK_DRILL_SET
 Bit 0 = Reverse the direction of spindle rotation during tapping
 Bit 1 = Boring (CYCLE86) Consider rotation of the tool plane
 Bit 2 = Boring (CYCLE86) Consider swiveled table kinematics
 Bit 3 = Tapping (CYCLE84) Monitoring spindle MD 31050/31060
 Bit 4 = Tapping (CYCLE840) Monitoring spindle MD 31050/31060
 Bit 5 = Tapping (CYCLE840) Calculation of the break point at G33

Boring

T D 1

F 50.000 mm/min
 S 2000.000 rpm
 Z1 25.000 inc
 DT 0.600 s
 SPOS 45.000 °
 No lift

Drilling

Accept



Notes

Program → Milling

SD55212 FUNCTION_MASK_TECH_SET
Bit 1 = 1 Calculate thread depth from metric thread lead
Note: As soon as the line table "None" is selected, the parameter H1 kann be overwritten

Thread milling

| | |
|-----------|-----------------|
| T | D 1 |
| F | 50.000 mm/min |
| S | 2000.000 rpm |
| Machining | 20 -> 21 |
| | RH thread |
| | Internal thread |
| NT | 3 |
| Z1 | 25.000 inc |
| Table | None |
| P | 2.000 mm/rev |
| ∅ | 6.000 |
| H1 | 1.000 |
| DXY | 0.100 inc |
| U | 0.300 |
| αS | 45.000 ° |

Buttons: Select tool, Graphic view, Cancel, Accept

Bottom bar: Edit, Drilling, Milling, Cont. mill., Various, Simulation, Execute

Program → Milling

Selection: M 2.5, M 3, M 3.5, M 4, M 4.5, M 5, M 6, M 8, M 10, M 12

Table: None, ISO metric, Whitworth BSW, Whitworth BSP, UNC

Thread milling

| | |
|-----------|-----------------|
| T | D 1 |
| F | 50.000 mm/min |
| S | 2000.000 rpm |
| Machining | 20 -> 21 |
| | RH thread |
| | Internal thread |
| NT | 3 |
| Z1 | 25.000 inc |
| Table | ISO metric |
| Select | M 12 |
| P | 1.750 mm/rev |
| ∅ | 10.106 |
| H1 | 0.947 |
| DXY | 0.100 inc |
| U | 0.300 |
| αS | 45.000 ° |

SD55212 FUNCTION_MASK_TECH_SET
Bit 2 = 1 Refer to the table for thread diameter and depth
Note: As soon as the line table "ISO metric" is selected, the table is activated for the various threads

Buttons: Select tool, Graphic view, Cancel, Accept

Bottom bar: Edit, Drilling, Milling, Cont. mill., Various, Simulation, Execute



Notes

Program → Contour milling

| Softkey selection | Description |
|-------------------|---|
| | |
| | |
| | |
| | |
| Option P13 | Residual material detection and machining |
| | |
| Option P13 | Residual material detection and machining |
| | |


Program → Simulation

| Softkey selection | Description |
|-------------------|---------------------------------|
| | |
| | |
| | |
| Option P25 | 3D simulation 1 (finished part) |
| | |
| | |
| | |




Notes

Program → Measure workpiece



Program → Measure tool



A110: END

Notes

