Installation Guide SINUMERIK 840Di sl SW 01.04.00.00

General notes on installation of the SINUMERIK 840Di sl software:

Required Hardware preconditions:

SINUMERIK 840Di sl consisting of:

- PCU50.3-C 1,5 GHz / PCU50.3-P 2,0 GHz

- MCI2-Board for SINUMERIK 840Di sl

The software will not operate on other hardware platforms.

Software preconditions:

Preinstalled PCU Base Software V08.00.01 or later (PCU Base Software for Windows XP SP2).

Special considerations when installing from Hard disk:

If the 840Di sl software is delivered on hard disk, the installation is automatically started when the control is switched on for the first time.

Software components included:

- SINUMERIK 840Di sl Base Software Version 04.40.09.00
- PLC Version 01.20.01.00 (PLC: 20.70.31.00, FB15: 01.04.05.00)
- HMI Base Software Version 07.03.00.00 (HMI internal: 07.30.23.00)
- HMI Base Hotfix Version 07.03.00.04 (HMI Base Hotfix internal: 07.30.23.04)
- HMI Advanced Hotfix Version 07.03.00.04 (HMI Advanced Hotfix internal: 07.30.23.04)
- PLC Toolbox CD Version 01.04.05.00
- SinuComNC Version 07.03.00.01 (SinuComNC internal: 07.30.08.00)
- NCK Version 01.30.08.00 (NCK: 67.05.04)
- PCU Base ServicePack Version 08.00.02.00 (PCU Base ServicePack internal: 08.00.31.00)
- PCU Base Hotfix Version 08.00.02.05 (PCU Base Hotfix internal: 08.00.31.11)
- ShopMill Version 07.20.05.00
- ShopTurn Version 07.20.11.00

Important Notes

- 1.) New functionality in SINUMERIK 840Di sl SW 01.04.00.00
- 2.) Compatibility
- 3.) Modifications for Setup
- 4.) SW licensing
- 5.) Tips and tricks
- 6.) General restrictions compared to catalogue and documentation
- 7.) Software installation from CD Rom via network connection
- 8.) Notes on ShopMill
- 9.) Notes on ShopTurn

1) New functionality in SINUMERIK 840Di sl SW 01.04.00.00

- SINUMERIK 840Di sl SW 01.04.00.00 supports ADI4
- SINUMERIK 840Di sl SW 01.04.00.00 can be used with ShopMill 7.2 and ShopTurn 7.2
- SINUMERIK 840Di sl SW 01.04.00.00 supports Ethernet MCP
- faster access by using changed SRAM access method
- SINUMERIK 840Di sl SW 01.04.00.00 supports Step7 and STARTER the control

2) Compatibility

SINUMERIK 840Di sl SW01.04.00.00 will only run with MCI2 board (for 840Di sl) and Windows XP

• SINUMERIK 840Di sl SW 01.04.00.00 is compatible with HMI Advanced 07.03.00.04 (Please refer to chapter 5, Tips and tricks and the compatibility list).

• SINUMERIK 840Di sl SW 01.04.00.00 is compatible with SIMATIC Step 7 for SINUMERIK Hardware V5.4 SP2.

• SINUMERIK 840Di sl SW 01.04.00.00 is compatible with SINAMICS 2.4. SINAMICS 2.3 can not be used.

• For Details please refer to the compatibility list.

3) Modifications for Setup

Conversion of existing NC/PLC Archives.

When converting from 840Di SW 3.x, it is necessary to create a new PLC hardware configuration by using the latest Version of "PLC Base program" (Toolbox V1.3.1).

Further information can be found in the 840Di sl manual.

Communication Settings.

Generally for communication from outside the PCU between HMI or engineering system (Step 7, Starter) and NC/PLC/drives Ethernet (also local HMI installed on PCU50) is used. Therefore, the program F:\mmc2\cp_840di.exe must be running. Cp_840di.exe is started automatically. Step7/STARTER installed on PCU based on Ethernet communication too. After installation of Step7/STARTER the interfaces in "PG/PC-interface" has to be changed. The access points s7online, Starter and SINUMERIK-CP must be set to Ethernet board (TCP/IP –Y Via R....) For local communication, also localhost address (127.0.0.1) is possible. These modifications must be done to connect from outside off the control. All other HMI application communicate via fast internal connection. All communication settings for SINUMERIK 840Di sI were done during installation.

```
4) SW licensing
```

The application of the SINUMERIK 840Di sl system software and its relevant options requires that the software licenses acquired are assigned for the hardware used.

This assignment is carried out via the Internet. You need the Certificate of License (CoL) for all licenses you want to assign. When entering the assignment data, you will receive a "License Key" linking the software and its options to the hardware.

You can easily set and activate the options and enter the "License Key" via the SinuCom NC operator interface. Without a valid "License Key", the control cyclically generates an alarm.

5) Tips and tricks

The PLC Toolbox is to be installed on the PC with Step7 which is used for programming the PLC for SINUMERIK 840Di sl SW 01.04.00.00. Drive OM is no longer required.

You can find Step7 example projects in "D:\setups\apps\001\000\support\840dismp\" on HD and in "\support\840dismp\" on CD.

840disl_tb145_DPMCP.zip 840disl_tb145_ETHMCP.zip 840disl_tb145_ETHMCP_HT8.zip for using a PROFIBUS machine control panel for using a PEthernet machine control panel for using a PEthernet machine control panel with HT8

for using a PROFIBUS-machine control panel in "D:\setups\apps\001\000\support\840dismp\840Di_sl_DPMCP_smpl.zip" on HD and in "\support\840dismp\840Di_sl_DPMCP_smpl.zip " on CD.

If you intend to use HMI Advanced on your 840Di, you will need Version 7.3.HF4, 7.3.1 SP1 or later.

Fast SRAM access is activated by default, but can be activated or deactivated in 849Di-Startup or HMI HMI-Advanced in Dialog NC/PLC-Diagnosis.

Machine data settings for ADI4

For compatibility with ADI4 drives you have to set the general machine data 13070[..] Drive_Function_mask = 80FH for the corresponding drive.

6) General restrictions compared to catalogue and documentation

- The PLC configuration has to be loaded also into the CP and afterwards the NCK has to be reset. If the subnet-ID has to be changed in the configuration (e. g. another project), the CP and HMI Advanced have to be stopped and restarted again. It is preferred to reboot the 840Di sl in this case.

- Important information for HD image compatibility:

The PCU50.3 will be shipped with a new revision of the main board, recognizable with type label VERS_GRBG. If an image created on PCU50.3 with a main board revision VERS_GRBG <=3 should be loaded on a PCU50.3 with a main board revision VERS_GRBG =>04, it is required, that the image is created under PCU Base 8.0 SP1 (V08.00.01.00). In order to do this, the PCU50.3 VERS_GRBG <=3 has to be updated to PCU Base 08.00 SP1 and the image has to be created again. Afterwards this image can be loaded on a PCU50.3 VERS_GRBG =>04. Please read also the installation guide of PCU Base 08.00 SP1.

Important: After restoring the image on the new PCU50.3 a HW detection will be performed by Windows XP. During this time, the mouse can not be used and a message window will appear. As soon as the mouse is operating again, the message can be acknowledged. Afterwards the PCU50.3 has to be switched off and on again.

7) Software installation from CD Rom via network connection

This type of installation requires a network connection of the PCU50 in order to transfer data directly to the hard disk of your PCU50.

Detailed information how to set up such a connection is to be found in the 840Di sl Manual chapter 15. The software to be installed is then copied to the directory D:\INSTALL on the PCU50 and will be installed automatically.

Alternatively:

The network connection is established under the Win desktop and the installation performed directly by calling SETUP.EXE from the supplied CD.

8) Notes on ShopMill

General:

Update in metric system of measurement only! The "Work step programming" option is necessary so that ShopMill programs can be created.

Machine data for ShopMill:

The file CMM.8x0 no longer exists, hence the listing of the machine data here. An overview is provided under the Tool operating area => Extended softkey bar => Machine data softkey. N10134 \$MN_MM_NUM_MMC_UNITS=6 ;minimum N10260 \$MN_CONVERT_SCALING_SYSTEM=1 :exact N10602 \$MN_FRAME_GEOAX_CHANGE_MODE=1 ;exact N10610 \$MN MIRROR REF AX=0 :exact N10700 \$MN PREPROCESSING LEVEL='H25' ;exact: bit0=1, bit2=1, bit5=1 N10702 \$MN IGNORE SINGLEBLOCK MASK='H10' ;exact: bit4=1 N10714 \$MN_M_NO_FCT_EOP=32 variable: N10715 \$MN_M_NO_FCT_CYCLE[0]=6 :variable N10716 \$MN M NO FCT CYCLE NAME[0]="L6" ;variable N10722 \$MN AXCHANGE MASK='H4' :exact: bit2=1 N10735 \$MN JOG MODE MASK='H1' :exact: bit0=1 N11270 \$MN_DEFAULT_VALUES_MEM_MASK='H1' ;exact: bit0=1 N11410 \$MN_SUPPRESS_ALARM_MASK='H7' ;exact: bit0=1, bit1=1, bit2=1 N11415 \$MN SUPPRESS ALARM MASK 2='H20' :exact: bit5=1 :exact: bit0=1, bit1=1, bit2=1 N11450 \$MN_SEARCH_RUN_MODE='H7' N11604 \$MN_ASUP_START_PRIO_LEVEL=1 ;minimum N17530 \$MN TOOL DATA CHANGE COUNTER='HF' ;exact: bit0=1, bit1=1, bit2=1, bit3=1 N18080 \$MN MM TOOL MANAGEMENT MASK='HB' ;exact: bit0=1, bit1=1, bit3=1 N18088 \$MN MM NUM TOOL CARRIER=1 ;minimum N18118 \$MN MM NUM GUD MODULES=7 :minimum N18120 \$MN MM NUM GUD NAMES NCK=20 ;minimum N18130 \$MN_MM_NUM_GUD_NAMES_CHAN=250 ;minimum N18150 \$MN MM GUD VALUES MEM=50 ;minimum N18160 \$MN_MM_NUM_USER_MACROS=30 ;minimum N18170 \$MN_MM_NUM_MAX_FUNC_NAMES=160 ;minimum N18180 \$MN MM NUM MAX FUNC PARAM=2000 :minimum N18280 \$MN MM NUM FILES PER DIR=400 :minimum N18320 \$MN MM NUM FILES IN FILESYSTEM=400 ;minimum :exact: bit0=1, bit6=1, bit14=1 N20110 \$MC_RESET_MODE_MASK='H4041' N20112 \$MC_START_MODE_MASK='H400' :exact: bit10=1 N20126 \$MC_TOOL_CARRIER_RESET_VALUE=0 :variable N20128 \$MC_COLLECT_TOOL_CHANGE=0 :exact N20130 \$MC CUTTING EDGE RESET VALUE=1 ;exact N20150 \$MC GCODE RESET VALUES[15]=3 ;exact N20150 \$MC_GCODE_RESET_VALUES[41]=1 ;exact N20150 \$MC GCODE RESET VALUES[51]=2 :exact N20150 \$MC_GCODE_RESET_VALUES[52]=1 ;variable (1=normal, >1 for Hirth-swivelheads)

N20152 \$MC_GCODE_RESET_MODE[5]=1 ;exact N20152 \$MC GCODE RESET MODE[7]=1 ;exact N20152 \$MC GCODE RESET MODE[12]=0 :exact N20202 \$MC_WAB_MAXNUM_DUMMY_BLOCKS=10 ;minimum N20240 \$MC CUTCOM MAXNUM CHECK BLOCKS=4 ;exact N20250 \$MC_CUTCOM_MAXNUM_DUMMY_BLOCKS=5 ;exact N20310 \$MC_TOOL_MANAGEMENT_MASK='H80400B' ;exact: bit0,1,3,14,23=1 N20320 \$MC TOOL TIME MONITOR MASK='H1' ;exact: bit0=1 N20734 \$MC EXTERN FUNCTION MASK='H8' ;exact: bit3=1 N22550 \$MC_TOOL_CHANGE_MODE=1 ;exact N22560 \$MC_TOOL_CHANGE_M_CODE=206 ;variable :exact N21100 \$MC_ORIENTATION_IS_EULER=0 N24006 \$MC CHSFRAME RESET MASK='H11' :exact: bit0=1, bit4=1, bit5=0 N24007 \$MC_CHSFRAME_RESET_CLEAR_MASK='H20'; exact: bit0=0, bit5=1 N24008 \$MC CHSFRAME POWERON MASK='H0' ;exact: bit0=0, bit5=0 N24805 \$MC TRACYL ROT AX FRAME 1=1 :exact N24855 \$MC TRACYL ROT AX FRAME 2=1 ;exact N27860 \$MC PROCESSTIMER MODE='H33' ;exact: bit0=1, bit1=1, bit4=1, bit5=1 N27880 \$MC_PART_COUNTER='H101' :variable N28000 \$MC_MM_REORG_LOG_FILE_MEM=75 ;minimum N28010 \$MC MM NUM REORG LUD MODULES=20 :minimum N28020 \$MC MM NUM LUD NAMES TOTAL=800 ;minimum N28040 \$MC MM LUD VALUES MEM=200 ;minimum N28082 \$MC MM SYSTEM FRAME MASK='H3D' ;exact: bit0=1, bit2=1, bit3=1, bit4=1, bit5=1 N28083 \$MC_MM_SYSTEM_DATAFRAME_MASK='H1F' ;exact: bit0=1, bit5=0, bit6=0 N28400 \$MC MM ABSBLOCK=1 :exact N28402 \$MC_MM_ABSBLOCK_BUFFER_CONF[0]=2 :exact N28402 \$MC_MM_ABSBLOCK_BUFFER_CONF[1]=4 ;exact N28450 \$MC MM TOOL DATA CHG BUFF SIZE=80 ;minimum N28560 \$MC MM SEARCH RUN RESTORE MODE='H1' :exact: bit0=1 N35040 \$MA SPIND ACTIVE AFTER RESET[?]=2 ;exact, ?= axis index for tool spindle N42440 \$SC FRAME OFFSET INCR PROG=0 ;exact N42442 \$SC TOOL OFFSET INCR PROG=0 :exact N42528 \$SC CUTCOM DECEL LIMIT=0.1 ;variable N42980 \$SC TOFRAME MODE=2000 ;exact Recent additions to range of display machine data: N9718 \$MM CMM OPTION MASK 2='H200' :mask out variable MD overview N9739 \$MM CMM M CODE TOOL FUNC 1 ON N9740 \$MM_CMM_M_CODE_TOOL_FUNC_1_OFF N9741 \$MM CMM M CODE TOOL FUNC 2 ON N9742 \$MM_CMM_M_CODE_TOOL_FUNC_2_OFF N9743 \$MM CMM M CODE TOOL FUNC 3 ON N9744 \$MM_CMM_M_CODE_TOOL_FUNC_3_OFF N9745 \$MM_CMM_M_CODE_TOOL_FUNC_4_ON N9746 \$MM CMM M CODE TOOL FUNC 4 OFF

When the software is updated, the display machine data are not overwritten with default values. They must therefore be checked according to the Description of Functions.

For using ShopMill and ShopTurn on 840Di sl SW 1.1 you have to set the following machine data in addition:

- For precompiled cycles: 18351 \$MN_MM_DRAM_FILE_MEM_SIZE = 2000
- For spindle load meter: With Simodrive 611U and default Profibus telegram you have to set bit 10 in display machine data 9719 (read spindle load from drive).

Otherwise it is necessary to use free Profibus telegram configuration (optional)

With Sinamics Profibus telegram you have to set bit 10 in display machine data 9719 to 0 (read spindle load from drive). In this case the spindle load will be transferred via Profibus telegram 116 and processed in the 840Di sl.

PLC interface:

The ShopMill PLC is dispensed with. The adjustment of the interface signals is described in the ShopMill Description of Functions, in Chapter 6.

In the OB100, during the FB1 call, the parameter MMCToIF = True (transfer of the MMC signals to the interface...operating types, program influence) must be set. If the parameter is not set to TRUE, no operating mode change commands (on program selection) or program controls (program test, dryrun...) can be implemented via the interface.

Installation/upgrade on PCU50.3:

Requirements:

If you wish to install ShopMill on the PCU 50.3, the HMI Advanced software (see SINUMERIK 840D sl compatibility list for version) must already be installed on the PCU 50.3. The internal HMI must be deactivated via WINSCP. Call point "Open Terminal" under Commands. You can now run the command sc disable hmi or sc enable hmi in the command line.

In addition, check the version of the cycle support. The cycle support files for the measuring cycles (MCSUPP.ARC) and standard cycles (SCSUPP.ARC) are stored under Archive\Cycle archives.

Installation/software upgrade with USB on PCU 50.3

Copy the contents to any directory of the USB hardware (stick; card reader; etc.). Power up the PCU50 at the desktop.

Power on the PCU50, press key "3" when the message with the PCU Base Software version is displayed (e.g. V08.xx.xx.xx) and enter the password (e.g. SUNRISE). Connect the USB hardware to the USB front connection of the OP, for example. After WIN-XP has recognized the hardware, copy the directory contents to D:\INSTALL.

Installing the software:

Power OFF/ON the PCU50. The software is installed automatically when the PCU software is powered up or when SETUP.EXE is called from directory D:\INSTALL. Call SETUP.EXE during installation to delete the contents of D:\INSTALL prior to PCU50 power OFF in order to avoid duplication of the installation after PCU50 power OFF/ON.

Installation/software upgrade on PCU 50.3 via network

This installation method can be used only if the PCU50 has an existing network link which allows data to be transferred directly to the PCU50 hard disk.

Copy the contents to any directory of a networked PC/PG.

Power up the PCU50 at the desktop.

Power on the PCU50, press key "3" when the message with the PCU Base Software version is displayed (e.g. V08.xx.xx.xx) and enter the password (e.g. SUNRISE). Then copy all files from the installation package via network to D:\INSTALL of the PCU50.

Installing the software:

Power OFF/ON the PCU50. The software is installed automatically when the PCU software is powered up or when SETUP.EXE is called from directory D:\INSTALL. Call SETUP.EXE during installation to delete the contents of D:\INSTALL prior to PCU50 power OFF in order to avoid duplication of the installation after PCU50 power OFF/ON.

Procedure for NCK update:

- Save GUD (Global User Data) (NC Active Data => User Data => User Data
 Complete => Data Out in Archive)
- Create NCK and PLC archives; to do this, switch PLC to stop and back up display machine data
- Load / insert current NCK
- o Perform a general reset
- Read in NCK and PLC archives
- Adapt machine data, take note of alarm 4400 if it is displayed!
- o Unload / delete definitions
- o Cycles and definitions from ShopMill with HMI on NCU:

Read in the Define archives from the Services\Cycle archive\Standard cycles\defines.arc, Swquencer cycles\sm_def_e.arc and Measuring cycles\defines.arc and activate the definitions (SMAC.DEF, GUD5.DEF, GUD6.DEF and GUD7.DEF).

Read in the Cycle archives from Services\Cycle Archive\Standard cycles\cycles.arc, sequence cycles\sm cyc e.arc, Measuring cycles\mcycles.arc & jogmcyc.arc.

• Cycles and definitions from ShopMill with PCU 50.3:

Read in the Define archive from Services\Archive area SM_DEF.ARC. Load the definitions (GUD7_JS.DEF, GUD7_MC.DEF, GUD7_SC.DEF, GUD7_SM.DEF, SMAC_SC.DEF and SMAC_SM.DEF) and activate definitions SMAC.DEF, GUD5.DEF, GUD6.DEF and GUD7.DEF.

Read in the Cycle archive from Services\Archive area SM_CYC.ARC and load the cycles to the manufacturer and standard cycles directory if necessary. (Attention: adapt cycles CYCLE198.SPF and CYCLE199.SPF if necessary after consultation

- with the machine manufacturer).
- Read in GUD data (Data In => from archive)
- Reset the NCK
- Delete workpiece TEMP

The system cycle "Prog_Event" is used by the standard cycles and by ShopMill. If "Prog_Event" is also required to implement user functions, it must be ended by means of the M function from machine data N10714 \$MN_M_NO_FCT_EOP. If you create a cycle with the name CYCPE1US.SPF or CYCPE1MA.SPF, it will be called before the Siemens calls in Prog_Event. If you create a cycle with the name CYCPE_US.SPF or CYCPE_MA.SPF, it will be called after the Siemens calls. These cycles can be stored under User cycles or OEM cycles, as "Prog_Event" is overwritten in the OEM cycle directory during upgrading.

Restrictions which apply to ShopMill:

- A successful machine test (segment-specific test according to acceptance protocol) is required for the release of the following function:
 Automatic measuring systems for tool measuring
- When 0 is entered for the setup feedrate in ShopMill under "Settings", the axes will traverse at the velocity specified in machine data 32020.
- You can only use a TOA area.

9) Notes on ShopTurn

General:

Update in metric system of measurement only! The "Machining step programming" option is required to create ShopTurn programs. Tool type Stop has been assigned number 730. Number 750 was used for the Stop tool in ShopTurn before. The change represents an adaptation to HMI Advanced.

Machine data for ShopTurn:

File ST.8x0 is no longer existing, therefore the machine data are listed here. An overview is provided under the Tool operating area => Extended softkey bar => Machine data softkey. N10134 \$MN_MM_NUM_MMC_UNITS=6 ;minimum N10260 \$MN_CONVERT_SCALING_SYSTEM=1 ;exact N10602 \$MN FRAME GEOAX CHANGE MODE=1 ;exact N10610 \$MN MIRROR REF AX=0 :exact N10700 \$MN PREPROCESSING LEVEL='H25' ;exact: bit0=1, bit2=1, bit5=1 N10702 \$MN IGNORE SINGLEBLOCK MASK='H10' :exact: bit4=1 ;variable N10714 \$MN_M_NO_FCT_EOP=32 N10722 \$MN_AXCHANGE_MASK='H4' :exact: bit2=1 N10735 \$MN JOG MODE MASK='H1' :exact: bit0=1 N11270 \$MN_DEFAULT_VALUES_MEM_MASK='H1' :exact: bit0=1 N11346 \$MN_HANDWH_TRUE_DISTANCE=2 ;variable N11410 \$MN_SUPPRESS_ALARM_MASK='H1007' :exact: bit0=1. bit1=1, bit2=1, bit12=1 N11415 \$MN_SUPPRESS_ALARM_MASK_2='H20' :exact: bit5=1 N11450 \$MN_SEARCH_RUN_MODE='H7' ;exact: bit0=1, bit1=1, bit2=1 N11470 \$MN REPOS MODE MASK='H8' :exact: bit3=1 N11604 \$MN_ASUP_START_PRIO_LEVEL=1 ;minimum N17530 \$MN TOOL DATA CHANGE COUNTER='HF' ;exact: bit0=1, bit1=1, bit2=1, bit3=1 N18080 \$MN_MM_TOOL_MANAGEMENT_MASK='HB' ;exact: bit0=1, bit1=1, bit3=1 N18118 \$MN MM NUM GUD MODULES=7 ;minimum N18120 \$MN_MM_NUM_GUD_NAMES_NCK=20 ;minimum N18130 \$MN MM NUM GUD NAMES CHAN=300 ;minimum N18150 \$MN MM GUD VALUES MEM=120 :minimum N18160 \$MN MM NUM USER MACROS=30 ;minimum N18170 \$MN_MM_NUM_MAX_FUNC_NAMES=200 ;minimum N18180 \$MN_MM_NUM_MAX_FUNC_PARAM=3000 ;minimum N18280 \$MN_MM_NUM_FILES_PER_DIR=400 ;minimum N18320 \$MN_MM_NUM_FILES_IN_FILESYSTEM=400 :minimum N20090 \$MC SPIND DEF MASTER SPIND=? :exact ?= master spindle number from MD35000 N20110 \$MC_RESET_MODE_MASK='H04041' ;exact: bit0=1, bit6=1, bit14=1, bit16=0

N20112 \$MC_START_MODE_MASK='H400' ;exact: bit10=1 N20128 \$MC_COLLECT_TOOL_CHANGE=0 ;exact N20130 \$MC CUTTING EDGE RESET VALUE=1 ;exact N20150 \$MC_GCODE_RESET_VALUES[5]=2 ;exact N20150 \$MC_GCODE_RESET_VALUES[15]=3 :variable N20150 \$MC_GCODE_RESET_VALUES[48]=3 ;variable N20152 \$MC_GCODE_RESET_MODE[5]=0 ;exact N20152 \$MC GCODE RESET MODE[7]=1 ;exact N20152 \$MC GCODE RESET MODE[12]=0 ;exact N20152 \$MC_GCODE_RESET_MODE[14]=1 ;exact N20152 \$MC_GCODE_RESET_MODE[15]=0 ;exact N20202 \$MC_WAB_MAXNUM_DUMMY_BLOCKS=10 :minimum N20240 \$MC CUTCOM MAXNUM CHECK BLOCKS=4 ;exact N20250 \$MC_CUTCOM_MAXNUM_DUMMY_BLOCKS=5 ;exact N20310 \$MC TOOL MANAGEMENT MASK='H81400B' ;exact: bit0, 1, 3, 14, 16, 23 = 1N20320 \$MC_TOOL_TIME_MONITOR_MASK='H1' :exact: bit0=1 N20734 \$MC EXTERN FUNCTION MASK='H8' ;exact: bit3=1 N24006 \$MC_CHSFRAME_RESET_MASK='H1' ;exact: bit0=1, bit5=0 N24007 \$MC_CHSFRAME_RESET_CLEAR_MASK='H20'; exact: bit0=0, bit5=1 N24008 \$MC CHSFRAME POWERON MASK='H0' :exact: bit0=0. bit5=0 N24040 \$MC_FRAME_ADAPT_MODE='H7' ;exact: bit0=1, bit1=1. bit2=1 N24805 \$MC TRACYL ROT AX FRAME 1=2 :exact N24855 \$MC_TRACYL_ROT_AX_FRAME 2=2 ;exact *1) N24905 \$MC TRANSMIT ROT AX FRAME 1=2 :exact N24911 \$MC TRANSMIT POLE SIDE FIX 1=1 :exact N24955 \$MC_TRANSMIT_ROT_AX_FRAME_2=2 ;exact *1) N24961 \$MC TRANSMIT POLE SIDE FIX 2=1 ;exact *1) N27100 \$MC ABSBLOCK FUNCTION MASK='H1' :exact: bit0=1 N27860 \$MC PROCESSTIMER MODE='H33' ;exact: bit0=1, bit1=1, bit4=1, bit5=1 N27880 \$MC_PART_COUNTER='H101' :variable N28000 \$MC MM REORG LOG FILE MEM=75 ;minimum N28010 \$MC MM NUM REORG LUD MODULES=20 ;minimum N28020 \$MC MM NUM LUD NAMES TOTAL=1000 ;minimum N28040 \$MC MM LUD VALUES MEM=200 ;minimum N28082 \$MC MM SYSTEM FRAME MASK='H61' ;exact: bit0=1, bit5=1, bit6=1 N28083 \$MC_MM_SYSTEM_DATAFRAME_MASK='H1F' ;exact: bit0, 1, 2, 3, 4=1, bit5=0, bit6=0 N28400 \$MC_MM_ABSBLOCK=1 ;exact N28402 \$MC MM ABSBLOCK BUFFER CONF[0]=2 ;exact N28402 \$MC_MM_ABSBLOCK_BUFFER_CONF[1]=4 :exact N28450 \$MC MM TOOL DATA CHG BUFF SIZE=80 ;minimum N28560 \$MC_MM_SEARCH_RUN_RESTORE_MODE='H1' ;exact: bit0=1 N32084 \$MA_HANDWH_STOP_COND[?]=0xFF ;variable for X, Z and Y, if required N35035 \$MA_SPIND_FUNCTION_MASK[?]='H110' ;exact: bit10=0, ?= axis index main spindle

N35035 \$MA_SPIND_FUNCTION_MASK[?]='H110' ;exact: bit10=0, ?= axis index counterspindle *1) N35035 \$MA_SPIND_FUNCTION_MASK[?]='H110' ;exact: bit10=0, ?= axis index tool spindle *2) N35040 \$MA_SPIND_ACTIVE_AFTER_RESET[?]=2 ;exact, ?= axis index for main spindle N35040 \$MA_SPIND_ACTIVE_AFTER_RESET[?]=2 bit10=0, ?= axis index for counterspindle *1) N35040 \$MA SPIND ACTIVE AFTER RESET[?]=2 ;exact, ?= axis index for tool spindle *2) N37050 \$MA_FIXED_STOP_ALARM_MASK[?]=2 ;exact, ?= axis index for 4^{th} axis *1) N41100 \$SN JOG REV IS ACTIVE=0x0E ;variable *3) N42440 \$SC_FRAME_OFFSET_INCR_PROG=0 ;exact N42442 \$SC TOOL OFFSET INCR PROG=0 :exact ;variable N42528 \$SC CUTCOM DECEL LIMIT=0.1 N42940 \$SC TOOL LENGTH CONST=18 ;exact N42950 \$SC TOOL LENGTH TYPE=2 ;exact N42600 \$SC_JOG_FEED_PER_REV_SOURCE=0 ;exact: 0;-3 Default: 0 *3) N43300 \$SA_ASSIGN_FEED_PER_REV_SOURCE=0 ;exact: 0;-3 default: 0 for X, Z and Y, if required *3)

*1) with counterspindle only

*2) with tool spindle only

*3) with Manual Machine option only

Recent additions to range of display machine data:

N9428 \$MM_MA_SPIND_MAX_POWER=100 N9429 \$MM_MA_SPIND_POWER_RANGE=200 N9718 \$MM_CMM_OPTION_MASK_2='H200' variable MD overview N9729 \$MM_CMM_G_CODE_TOOL_CHANGE_PROG=-N9777 \$MM_CMM_ENABLE_TIME_DISPLAY='H7F' N9836 \$MM_ST_TAILSTOCK_DIAM=0 N9837 \$MM_ST_TAILSTOCK_LENGTH=0 N9838 \$MM_ST_BORDER_TOOL_LEN_X_REV_2=0 tool holders only N9897 \$MM_ST_OPTION_MASK_MAN_FUNC=0 N9899 \$MM_ST_TRACE=0 When the software is upgraded, the already existing display mack

variable; variable; mask out;

;variable ;variable ;variable ;variable

variable, >0 for 2;

;variable ;variable

When the software is upgraded, the already existing display machine data are not initialized with defaults. For this reason, they should be checked according to the Description of Functions.

Machine data for a second tool holder on the X axis:

- A tool length, where the tools start to be located on a 2nd turret is defined through a display machine data (= = no 2nd turret available): 9838
 \$MM_ST_BORDER_TOOL_LEN_X_REV_2
- For a proper function of the TNRC in the mirrored coordinate system CUT2DF must always be selected: (is set automatically in F_HEAD)
 20150 \$MC_GCODE_RESET_VALUES[21]=2 ; exact
 20152 \$MC_GCODE_RESET_MODE[21]=0 ; exact
- The following MD must be set so that LIFTFAST (thread cutting retraction) also reacts to the mirror:
 21202 \$MC_LIFTFAST_WITH_MIRROR = 1 ; exact
- WPFRAME is required for mirrors and offsets:
 24006 \$MC_CHSFRAME_RESET_MASK Bit 4=1 (='H11')
 24007 \$MC_CHSFRAME_RESET_CLEAR_MASK Bit 4=0 (='H00')
 28082 \$MC_MM_SYSTEM_FRAME_MASK Bit 4=1 (='H31')
 28083 \$MC_MM_SYSTEM_DATAFRAME_MASK Bit 4=1 ('H1F')
- Tool wear must be mirrored as well:
 42910 \$SC_MIRROR_TOOL_WEAR = 1 ; exact

For using ShopMill and ShopTurn on 840Di sl SW 1.1 you have to set the following machine data in addition:

- For precompiled cycles: 18351 \$MN_MM_DRAM_FILE_MEM_SIZE = 2000
- For spindle load meter:
 With Simodrive 611U and default Profibus telegram you have to set bit 10 in display machine data 9719 (read spindle load from drive).
 Otherwise it is necessary to use free Profibus telegram configuration (optional)

With Sinamics Profibus telegram you have to set bit 10 in display machine data 9719 to 0 (read spindle load from drive). In this case the spindle load will be transferred via Profibus telegram 116 and processed in the 840Di sl.

PLC interface:

The ShopTurn PLC is omitted. The adaptation of the interface signals is described in the description of functions for ShopTurn provided in chapter 6.

In the OB100, during the FB1 call, the parameter MMCToIF = True (transfer of the MMC signals to the interface...operating types, program influence) must be set. If the parameter is not set to TRUE, no operating mode change commands (on program selection) or program controls (program test, dryrun...) can be implemented via the interface.

The manual tool function (e.g. for multifix holder) can be used under the following conditions:

N22550 TOOL_CHANGE_MODE = 0

N22562 TOOL_CHANGE_ERROR_MODE ='H2'

The interface signals in the PLC behave as follows:

- Changing from T0 to a tool from the turret and vice versa activates DB73
- Changing from T0 to a manual tool and vice versa activates DB72 with loading/unloading the manual tool
- Changing from a tool from the turret to a manual tool first activates DB73 with T0 and then DB72 with loading of manual tool
- Changing from a manual tool to a tool from the turret activates DB73 with unloading manual tool (DBX 4.6)

PLC sample modules are available in the tool box under \8x0d\ShopMill_Turn\ShopTurn\tm_rev_xy.awl.

Installation/upgrade on PCU50.3:

Requirements:

If you wish to install ShopTurn on the PCU 50.3, the HMI Advanced software (see SINUMERIK 840D sl compatibility list for version) must already be installed on the PCU 50.3. The internal HMI must be deactivated via WINSCP. Call point "Open Terminal" under Commands. You can now run the command sc disable hmi or sc enable hmi in the command line.

In addition, check the version of the cycle support. The cycle support files for the measuring cycles (MCSUPP.ARC) and standard cycles (SCSUPP.ARC) are stored under Archive\Cycle archives.

Installation/software upgrade with USB on PCU 50.3

Copy the contents to any directory of the USB hardware (stick; card reader; etc.). Power up the PCU50 at the desktop.

Power on the PCU50, press key "3" when the message with the PCU Base Software version is displayed (e.g. V08.xx.xx.xx) and enter the password (e.g. SUNRISE).

Connect the USB hardware to the USB front connection of the OP, for example. After WIN-XP has recognized the hardware, copy the directory contents to D:\INSTALL.

Installing the software:

Power OFF/ON the PCU50. The software is installed automatically when the PCU software is powered up or when SETUP.EXE is called from directory D:\INSTALL.

Call SETUP.EXE during installation to delete the contents of D:\INSTALL prior to PCU50 power OFF in order to avoid duplication of the installation after PCU50 power OFF/ON.

Installation/software upgrade on PCU 50.3 via network

This installation method can be used only if the PCU50 has an existing network link which allows data to be transferred directly to the PCU50 hard disk.

Copy the contents to any directory of a networked PC/PG.

Power up the PCU50 at the desktop.

Power on the PCU50, press key "3" when the message with the PCU Base Software version is displayed (e.g. V08.xx.xx.xx) and enter the password (e.g. SUNRISE). Then copy all files from the installation package via network to D:\INSTALL of the PCU50.

Installing the software:

Power OFF/ON the PCU50. The software is installed automatically when the PCU software is powered up or when SETUP.EXE is called from directory D:\INSTALL. Call SETUP.EXE during installation to delete the contents of D:\INSTALL prior to PCU50 power OFF in order to avoid duplication of the installation after PCU50 power OFF/ON.

Procedure for NCK update:

- Save GUD (Global User Data) (NC Active Data => User Data => User Data Complete => Data Out in Archive)
- Create NCK and PLC archives; to do this, switch PLC to stop and back up display machine data
- o Load / insert current NCK
- Perform a general reset
- Read in NCK and PLC archives
- Adapt machine data, take note of alarm 4400 if it is displayed!
- o Unload / delete definitions
- Cycles and definitions from ShopTurn with HMI on NCU:

Read in the Define archives from Services\Cycle Archive area standard

cycles\defines.arc, sequence cycles\st_def_e.arc, measuring cycles\defines.arc. Activate definitions (SMAC.DEF, GUD5.DEF, GUD6.DEF and GUD7.DEF)

Read in the Cycle archives from Services\Cycle Archive standard cycles\cycles.arc, sequence cycles\st_cyc_e.arc, measuring cycles\mcycles.arc.

• Cycles and definitions from ShopTurn with PCU 50.3:

Read in the Define archive from Services\Archive area ST_DEF.ARC. Load definitions (GUD7_JS.DEF, GUD7_MC.DEF, GUD7_SC.DEF, GUD7_ST.DEF, SMAC_SC.DEF and SMAC_ST.DEF) and activate definitions SMAC.DEF, GUD5.DEF, GUD6.DEF and GUD7.DEF.

Read in the cycle archive from Services\Archives\ST_CYC.ARC and load the cycles to the manufacturer and standard cycles directory if necessary

(Attention: Adapt cycles ST_CUST.SPF(cyccust_gr.arc), CYCLE198.SPF and CYCLE199.SPF if necessary after consultation with the machine manufacturer).

- Read in GUD data (Data In => from archive)
- Reset the NCK
- Delete workpiece TEMP

System cycle "Prog_Event" is utilized by the standard cycles and by ShopTurn. If "Prog_Event" is also required to implement user functions, it must be ended by means of the M function from machine data N10714 \$MN_M_NO_FCT_EOP. If you create a cycle with the name CYCPE1US.SPF or CYCPE1MA.SPF, it will be called before the Siemens calls in Prog_Event. If you create a cycle with the name CYCPE_US.SPF or CYCPE_MA.SPF, it will be called after the Siemens calls. These cycles can be stored under User cycles or OEM cycles, as "Prog_Event" is overwritten in the OEM cycle directory during upgrading.

Restrictions which apply to ShopTurn:

- A machine test (segment-specific test according to acceptance protocol) is required for the release of the following functions:
 - Automatic measuring systems for tool measuring
- You can only use a TOA area.
- T=location number exclusively refers to the first turret / tool holder.
- o The active location is not displayed with two turrets.
- The Manual Machine option does not support any counterspindle.
- For the manual machine version, a 0 can be entered in the feed field mm/rot or mm/min. The axes will in this case traverse using the data of axis machine data 32020 or 32050.
- This behavior occurs in ShopTurn when 0 is entered for setup feed rate under "Settings".