ProTool V.6.0 Service Pack 3 Hotfix 3

Validity

This hotfix applies to version 6.0 plus SP3 of ProTool, ProTool/Pro, ProTool/Lite and ProAgent.

The described functionality is only guaranteed if you have completely installed this hotfix:
- ProTool, ProTool/Pro CS, ProAgent
- Image MP 370. The image can be loaded onto the device with ProSave.

Installation

Run \Disk1\SETUP.EXE to install this hotfix.

Modified functionality

1. Script Engine of Windows CE
In version V6.0 SP3, we notified you that runtime errors in scripts are to be avoided because they can lead to a continuous rise of the memory used. This procedure has been corrected.

2. ProAgent and WinAC MP License
The license requests for ProAgent and WinAC MP are synchronized.

3. ProAgent Screens
The change view of ProAgent screens has been optimized.

4. Touch Device
Sporadically, the touch device could only be operator-controlled using the mouse. This has been corrected.

5. Processing of Processor Commands in MP370
The processing of processor commands has been optimized.

6. Pocket Internet Explorer
The processing of HTML 3.0 Seiten has been optimized.
The Pocket Internet Explorer of HMI panels is only released for simple HTML pages based on HTML 3.0 standard.

7. PC-Loader
If you were logged in with user rights in the Windows system, the texts in the PC Loader were still partly in German, even if the language was set to English. The RT did not start automatically in this case.

8. Recipes
The system messages has been optimized.

9. Date and Time in WinCE devices
The output of date and time has been optimized.